


2-GCA-986


2-GCA-986 · Titanium 1.0i Ecoboost 100pk 74kw · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-GCA-986	Fuel Type	Gasoline
Manufacturer	FORD	VIN	WF0JXXGAHJPD28568
Model	Fiesta	Cylinder Capacity	998 ^{cm3}
Model Versions	Titanium 1.0i Ecoboost 100pk 74kw	Transmission Type	Handmatig geschakelde transmissie
		First Admission	06-04-2023
Body Type	5 door hatchback	Odometer	104.592 ^{Km}
Color	Grey	Numer Of Keys	2
Paint Type	Metallic	Interior	Grey
Production Year	2023	Number Headrests	5
KW	74		

Images





Accessories

ABS

Airbags

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Leather steering wheel

Rear parking sensors

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Windscreen - Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs

Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	1 ^{mm}	Delinte	195 ^{mm}	60 ^{mm}	15 ^{inch}	Summer
Rear Left	2 ^{mm}	Continental	195 ^{mm}	60 ^{mm}	15 ^{inch}	Summer
Front Right	1 ^{mm}	Delinte	195 ^{mm}	60 ^{mm}	15 ^{inch}	Summer
Rear Right	2 ^{mm}	Continental	195 ^{mm}	60 ^{mm}	15 ^{inch}	Summer
Spare Tire Type	Compressor					

Damages



Damage Part

Fender – Rear Right



Damage Type

small dents / small scratches



Repair Type

Panelbeating & Spray

Acceptable

No



Damage Part

Reardoor – Right



Damage Type

Small dent(s)



Repair Type

Restyle

Acceptable

No



Damage Part

Windscreen – Front



Damage Type

Scratch(es)

Repair Type

Polish

Acceptable

No



Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Right Front	Damaged	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Grille	Broken	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Left Front	Damaged	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Skirt - Left	Small scratch(es)	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Left	Door-edge chipped	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Left	Small scratch(es)	Acceptable	Yes



Damage Part
Bumper – Rear

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Tailgate

Damage Type
Small dent(s)

Repair Type
Restyle

Acceptable
No



Damage Part
Trunkshelf

Damage Type
Missing

Notes
Touwtjes

Repair Type	Acceptable
Replace	No