



**Mercedes Vito:**

Vinnumber:	<b>W1V44770313884192</b>	Versionname:	
First Registrationdate:	<b>23/06/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>99736</b>	Power Kw:	<b>100</b>
Bodytype:		Body colour:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Steel</b>
Transmission:		Parking lot:	<b>2623</b>
Fueltype:	<b>Diesel</b>		
Type of rims (mounted):	<b>Steel</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

**Options**

Number of keys total:	<b>2</b>	Rear parking sensors:	
Steering wheel multifunctional:		Type of Tow bar:	<b>Tow bar removable</b>
Radio multimedia:			
Type of headlighting:	<b>Headlighting Halogen</b>		
Type of GPS:	<b>No GPS</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Manual climate control</b>		

**Limited Technical Inspection**

**Tyres**

195/65/16/104 R				
Winter tyres:	Fr.L.	<b>Uniroyal: 4 mm</b>	Fr.R.	<b>Uniroyal: 4 mm</b>
	Re.L.	<b>Uniroyal: 4 mm</b>	Re.R.	<b>Uniroyal: 4 mm</b>
Tyre profile depth FL				<b>4.0</b>
Tyre profile depth FR				<b>4.0</b>
Tyre profile depth RL				<b>4.0</b>
Tyre profile depth RR				<b>4.0</b>
Tyre size FL				<b>195/65 R 16 104 R</b>
Tyre size FR				<b>195/65 R 16 104 R</b>
Tyre size RL				<b>195/65 R 16 104 R</b>
Tyre size RR				<b>195/65 R 16 104 R</b>
Tyre type FL				<b>Winter</b>
Tyre type FR				<b>Winter</b>
Tyre type RL				<b>Winter</b>
Tyre type RR				<b>Winter</b>
Tyre make FL				<b>265</b>
Tyre make FR				<b>265</b>
Tyre make RL				<b>265</b>
Tyre make RR				<b>265</b>

**Assistance equipment**

Number of charging cables (normal):	<b>0</b>
Number of charging cables (rapid charge):	<b>0</b>

Total cost ex VAT	<b>1644,05</b>
Interior, Damaged, Acceptable	<b>0,00</b>





Seat Mid R, complete, Missing, Check 0,00



Bumper F, Scratch(es), Acceptable 0,00



Wheel cover FL, Scratch(es), Acceptable 0,00



Door FL, Scratch(es), Repair and paint (complete) 334,34



Door RL, Scratch(es), Acceptable 0,00



Wheel cover RL, Scratch(es), Replace 25,50



Bumper R, Crack, Replace 345,50



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete) 625,96



Rear window, Scratch(es), Replace 312,75



Wheel cover FR, Scratch(es), Acceptable 0,00

