ARVAL
BNP PARIBAS GROUP

1XCF389

INSPECTION REPORT

End of contract


GENERAL INFO

File	322689
License plate	1XCF389
Vehicle identification number	WV2ZZZ7HZKH162440
Dossier	2019 148 136
Make	Volkswagen Multi.2.0TDi 150 Hi
Mileage	42317
First registration	14/11/2019
client availability date	25/09/2026
inspectionDate	01/10/2026







CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	




B
1 XCF 389

DAMAGES

Damages	Type	Acceptable
72	Side View Mirror Left // Painting	N
73	Side View Mirror Left // Replace Not Painted	N
183	Wing Rear Right // Painting	N
193	Door Rear Right // Painting	N
213	Door Front Right // Painting	N
103	Door Rear Left // Painting	N
113	Wing Rear Left // Painting	N
13	Bumper Front // Painting	N
54	Headlight / Front left / Replace	Y
83	Door Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
98	Rocker Panel Left / Cover Not Painted / Replace	Y
134	Bumper Rear // Repair & Painting	N
164	Roof // Replace & Painting	Y
244	Light / Front Right / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
340	Wheel Two Tone Front Right // Repair	N
411	Seat Front Left // Repair	N
453	Seat Rear Right / Rear Coating / Replace	N
532	Trunk Compartment / Side Cover Left / Replace	N
533	Trunk Compartment / Side Cover Right / Replace	N
534	Trunk Compartment / Carpet / Replace	N
539	Trunk Compartment / Back Coating / Replace	Y
540	Interior // Repair 1	N
541	Interior // Repair 2	N
544	Interior / Floor Covering / Replace	Y
549	Interior / Headliner/ Replace	Y
561	Dashboard // Repair	N
564	Dashboard // Replace Completely	Y
593	Trunk Lid Interior Coating / MDF Rear Right / Replace	N

594	Trunk Lid Interior Coating / Complete Panel / Replace	N
599	Trunk Lid Interior Coating / MDF Side Door Right / Replace	N
644	Rear Right Door Interior Coating // Replace Completely	N
772	Interior / A Pillar Upper Cover / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures





Trunk Lid Interior Coating / Complete Panel / Replace-scratch








Trunk Compartment / Side Cover Left / Replace-scratch




Trunk Lid Interior Coating / MDF Rear Right / Replace-scratch


Trunk Compartment / Side Cover Right / Replace-scratch


Wheel Two Tone Front Right // Repair-scratch








Bumper Front // Painting-scratch





Headlight / Front left / Replace-scratch




Wheel Two Tone Front Left // Repair-scratch




Dashboard // Repair-scratch




Dashboard // Replace Completely-scratch




Light / Front Right / Replace-scratch




Door Front Left // Painting-scratch






Rocker Panel Left // Smart Repair Medium-scratch




Seat Front Left // Repair-scratch






Trunk Compartment / Carpet / Replace-dent





Rocker Panel Left / Cover Not Painted / Replace-dent







Bumper Rear // Repair & Painting-scratch + dent


Trunk Compartment / Back Coating / Replace-missing




Interior // Repair 1-tear




Seat Rear Right / Rear Coating / Replace-tear



Interior // Repair 2-tear




Trunk Lid Interior Coating / MDF Side Door Right / Replace-tear




Rear Right Door Interior Coating // Replace Completely-tear



Interior / A Pillar Upper Cover / Replace-tear





Interior Cleaning // Small-stain






Interior / Headliner/ Replace-hole






Interior / Floor Covering / Replace-hole

Roof // Replace & Painting-hole




Side View Mirror Left // Painting-scratch

Side View Mirror Left // Replace Not Painted-scratch








Wing Rear Right // Painting-scratch






Door Rear Right // Painting-scratch






Door Front Right // Painting-scratch




Door Rear Left // Painting-scratch





Wing Rear Left // Painting-scratch