




IDENTIFICATION VEHICLE

Driver name:	HM Tongeren
Make:	AUDI
Model / version:	A3 SPORTBACK
Vin:	WAUZZZGY3NA006158
Plate:	
Mileage:	130987
First registration:	10/08/2021
Color:	Atolblauw me







ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✗
Registration certificate:	✗
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES





VIN INFORMATION

6 haut-parleurs
7 rapports
Matière : alliage
Diamètre arrière 17
Diamètre avant 17
Hauteur arrière 45
Largeur avant 225
Climatisation automatique
Diesel
85 kw
Métallisée vernissée
Volant cuir
Aide au stationnement arrière

Appel de secours
Airbag passager désactivable

radio avec récepteur numérique
enjolveurs bas de caisse éclairés
barre stabilisatrice av 24 mm

freins av 288x15

Téléphone
Equipeement S-Line
Lettre repère (J)
Largeur avant 8,0
Diamètre arrière 17
Indice de vitesse avant Y
Largeur arrière 225
Climatisation réfrigérant 1234YF
1968 cm3
115 ch
Rétroviseur gauche asphérique
Volant chauffant
Caméra avant

Pare-brise teinté dégradé
Freinage d'urgence assistée autonome (urbain)
garnissage tissu Index
205/55 R 17 .. W
sidebag av/ar avec airbag pour la tête et
airbag central av
FREINS AR 272X10

Transmission séquentielle
Becquet arrière
Diamètre avant 17
Largeur arrière 8,0
Hauteur avant 45
Indice de vitesse arrière Y
Chauffage supplémentaire
Accoudoir central avant
2.00 litres
Euro 6
Suspension sport
Volant multifonction
Affichage lecture des panneaux de signalisation
Airbag passager depuis 07.21

extincteur
système de gonflage des pneus
Système SCR (Selective Catalytic Reduction)

EQUIPMENT

Board computer: ?
Compressor: ✓
Gps: ?
Rear parking sensor: ?
Front seats heated: ?
Electric windows: ?
Headlighting type:
Charging cables: 0

Central locking: ?
Cruise control: ?
Power steering: ?
Repair kit: ✓
Steering wheel: ?
Climate control type:
Tow bar type:
Fast charging cables: 0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			Summer		?
Front right	5 mm			Summer		?
Rear left	5 mm			Summer		?
Rear right	5 mm			Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Contact key - Boordcomputer resetten	Not original part
2	Certificate of registration 1	Missing
3	Certificate of conformity	
4	Bumper spoiler F	Grooved
6	Alloy rim FL	Grooved
7	Inner door sill FL	Dent(s) and scratch(es)
8	Alloy rim RL	Grooved
9	Bumper R	Dent(s) and scratch(es)
10	Tailgate / Boot	Dent(s)
11	Wing RR	Dent(s) and scratch(es)
12	Alloy rim RR	Grooved
13	Alloy rim FR	Grooved
14	Windscreen	Crack

Total: 13


ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
5	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 1

DAMAGES DETAILS

1 - Contact key - Boordcomputer resetten - Not original part



2 - Certificate of registration 1 - Missing



3 - Certificate of conformity





4 - Bumper spoiler F - Grooved



6 - Alloy rim FL - Grooved



7 - Inner door sill FL - Dent(s) and scratch(es)




8 - Alloy rim RL - Grooved



9 - Bumper R - Dent(s) and scratch(es)



10 - Tailgate / Boot - Dent(s)



11 - Wing RR - Dent(s) and scratch(es)



12 - Alloy rim RR - Grooved



13 - Alloy rim FR - Grooved



14 - Windscreen - Crack



5 - Bodywork - Dent(s) and scratch(es) - Renta®



