MACADAM










Polestar 2: N300VB

Vinnumber:	**LPSVSECEKNL061825**	Versionname:	**Polestar 2 165kW/ 63kWh Single Motor Standard Range**
First Registrationdate:	**30/12/2021**	Fiscalpower:	
Expertise Mileage:	**153757**	Power Kw:	**165**
Bodytype:		Body colour	**Thunder (metallic)**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**1019**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Rear parking sensors	
GPS		Rear view camera	
Autom climate control			
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	245 / 45 / 19 / 102 / V / Aluminium	3,0 mm	Michelin	Summer
	Right	245 / 45 / 19 / 102 / V / Aluminium	3,1 mm	Michelin	Summer
Rear	Left	245 / 45 / 19 / 102 / V / Aluminium	4,4 mm	Michelin	Summer
	Right	245 / 45 / 19 / 102 / V / Aluminium	4,1 mm	Michelin	Summer

Assistance equipment

Number of charging cables (rapid charge)	**1**

Interior, Dirty, Cleaning




Wing RL, Dent(s), Repair and paint (complete)




Door FL, Scratch(es), Polish




Wing FL, Scratch(es), Repair and paint (complete)




Bonnet, Stone chip(s), Repair and paint (complete)




Bumper F, Scratch(es), Polish




Door RR, Scratch(es), Polish





Bumper R, Scratch(es), Polish





Boot lid covering R, Scratch(es), Replace




Onderhoudshistorie van: LPSVSECEKNL061825

ALPHABET

Kenteken	N300VB
Merk Model	Polestar Polestar 2 165kW/ 63kWh Single Motor Standard Range
Brandstofsoort	Elektrisch
Datum deel1	12/30/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
10/1/25	138,899	APK
10/1/25	138,899	Sleutelbatterij
8/25/25	136,880	Onderhoudsbeurt
3/10/25	119,914	Extra verwarmingselement
3/10/25	119,914	Isolatiemeting
3/10/25	119,914	Spanningsvrij
4/15/24	86,464	Reparatie band(en)
7/28/23	59,490	Onderhoudsbeurt
7/28/23	59,490	Volvo Check slijtagedelen
2/2/23	36,789	Vervanging band
12/6/22	28,699	Onderhoudsbeurt