APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	RENAULT
Model / version:	ARKANA
Vin:	VF1RJL006UC325244
Plate:	2CEC352
Mileage:	205573
SOH:	
First registration:	21/06/2022
Color:	Noir d'Ivoir

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓


PICTURES



























































VIN INFORMATION

depuis 02.22
vitres latérales et lunette ar teintées foncé (VSTLAR)
rétroviseurs électrique chauffants et rabattables automatique (RET04)
appareil de commande TCU (AIVCT)
feux de route et de croisement automatique (PRAHL)
volant en mousse 1 (VLMOU1)
architecture électronique (AVC1A)
série supplémentaire (ENPH01)
liquide de climatisation R1234yf (1234Y)
capteur d'angle mort (DANGMO)
feux de jour LED 3 (FDIU3)
sièges av Type N 05 (SGAV05)
tableau de bord numérique (MET04)
aide au parking av et ar (ITPK4)
climatisation automatique (CA02)
commande à distance 433 MHz (SOP03C)
système d'appel d'urgence (RCALL/PCALL)
essuie-glace avec allumage automatique des feux (ALEVA)
avertisseur de trafic latéral (RCTA0)
bruit de véhicule pour piétons (VSPTA)
caméra de marche arrière (RRCAM)

norme anti-pollution Euro 6d (E06U)	1598 cc (1,6 L) 69/70 KW LDMU 105/119 KW (Total)	équipement supplémentaire (SAN913)
4 vitesses automatique DB1	Full Hybrid (HYB05)	gestion de la vitesse (AVOSP1)
frein à main électrique (FPASS/FPAS2)	assistant de trajectoire (DLIGM2)	régulateur de vitesse (RV)
215/60 R 17 .. H	7 J x 17 Alu "BAHAMAS" (RALU17^RDIF03)	roue de secours temporaire (RSGALT)
système de freinage d'urgence (AEBS07)	code équipement (EA2)	2 couches métallisée

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	?	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	?
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:		**Fast charging cables:**	

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	4 mm	Continental	215601796h	Winter	Aluminium	×
Front right	4 mm	Continental	215601796h	Winter	Aluminium	×
Rear left	4 mm	Continental	215601796h	Winter	Aluminium	×
Rear right	4 mm	Continental	215601796h	Winter	Aluminium	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Bumper F	Scratch(es)
2	Door FL	Scratch(es)
2	Wing trim FL	Scratch(es)
4	Door RL	Dent(s)
6	Bumper R	Scratch(es)
7	Spoier bumper R	
8	Wing trim RR	Scratch(es)
10	Roof	

Total: 8

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
3	Outside rear-view mirror housing L	Scratch(es)	✓	×	×
9	Door FR	Scratch(es)	✓	×	×

Total: 2

DAMAGES DETAILS

1 - Bumper F - Scratch(es)






2 - Door FL - Scratch(es)



2 - Wing trim FL - Scratch(es)

4 - Door RL - Dent(s)




6 - Bumper R - Scratch(es)




7 - Spoier bumper R





8 - Wing trim RR - Scratch(es)





10 - Roof







3 - Outside rear-view mirror housing L - Scratch(es) - Renta®



5 - Wing RL



9 - Door FR - Scratch(es) - Renta®



SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert	Customer
27/10/2026 09:59	27/10/2026 09:59
	Useless