



HYUNDAI IONIQ: 3003-LNY

Vinnumber:	KMHC751CGMU250542	Versionname:	1.6 GDI HEV Klass DCT berlina con portón 104kW 5P automática
First Registrationdate:	27/04/2021	Fiscalpower:	
Expertise Mileage:	172459	Power Kw:	
Bodytype:	Berline	Body colour	Dark Grey
Gearbox:	Automatic	Type of rims (mounted)	Steel
Transmission:			
Fueltype:	Hybrid		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	2	Central consol F
Number keys remote	2	Luggage cover
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

	185/65/16/92 T			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				185/65 R 16 92 T
Tyre size FR				185/65 R 16 92 T
Tyre size RL				185/65 R 16 92 T
Tyre size RR				185/65 R 16 92 T
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Interior, Dirty, Cleaning





Boot lid covering R, Scratch(es), Replace



Door panel RL, Scratch(es), Replace



Seat cover FL, Burned, Replace



Steering wheel, Scratch(es), Acceptable



Floor covering FL, Tear, Replace



Registration document, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Door FL, Scratch(es), Repair and paint (complete)



Door trim RL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Wheel cover RL, Scratch(es), Replace



Bumper trim F, Scratch(es), Acceptable



Wing RR, Dent(s), Repair and paint (complete)



Wheel cover RR, Broken, Replace



Wheel cover FR, Broken, Replace



Door FR, Scratch(es), Repair and paint (complete)



Door trim RR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Wing FR, Dent(s), Repair and paint (complete)



Tailgate / Boot, Dent(s), Repair and paint (complete)



Tyres, No damage, Check



Datos del vehículo

Marca	Matrícula
Modelo	VIN
Versión	

Histórico

Fecha	Descripción	Kilómetros	Taller

Datos del vehículo

Marca

Modelo

Versión

Matrícula

VIN

Histórico

Fecha	Descripción	Kilómetros	Taller