

2-DRE-503

2-DRE-503 · ST-line 125pk 92kw mHEV M6 Clipper · 21 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-DRE-503	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WF0PXXGCHPPL84622
Model	Focus	Cylinder Capacity	999 ^{cm3}
Model Versions	ST-line 125pk 92kw mHEV M6 Clipper	Transmission Type	Handmatig geschakelde transmissie
Body Type	5 door hatchback	First Admission	02-06-2023
Color	Grey	Odometer	76.939 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2023	Interior	Black
KW	92	Number Headrests	5

Images





Accessories

ABS	Electric windows front
Airbags	Electrically adjustable exterior mirrors
Alloy wheels	Front & rear parking sensors
Audio System	Leather steering wheel
Automatic air conditioning	Navigation system
Bluetooth car kit	Roller cover / parcel shelf
Central door locking	Seat heating
Centre armrest	Steering wheel multifunction
Cruise control	Steeringwheel - Heated
Electric rear windows	Windscreen - Heated

Condition

Condition exterior Adequate	Last Maintenance Unknown
Condition interior Adequate	Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	1 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Left	5 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Front Right	1 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Right	5 ^{mm}	Delinte	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Missing	Reservesleutel	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Small scratch(es)	Touch-up / Polish	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	Small dent(s)	Stijl	Restyle	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Dent(s) & Scratch(es)	Replace & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Front	Damaged	Rim repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Right	Door-edge chipped	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	Small dent(s)	Restyle	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No