MACADAM







Volkswagen Passat (KKL): 2CGM957

Vinnumber:	**WVWZZZ3CZNE075647**	Versionname:	**Passat Variant GTE Business 1.4TSi 218pk/cv 5p DSG6**
First Registrationdate:	**15/07/2022**	Fiscalpower:	
Expertise Mileage:	**103344**	Power Kw:	**115**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Plug-in Hybrid Petrol**		
Maintenance	**NOT OK**		
Maintenance	**min 3800 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**215/55/17/98 W**			
	Fr.L.	**Firestone: 3 mm**	Fr.R.	**Firestone: 4 mm**
	Re.L.	**Continental: 3 mm**	Re.R.	**Continental: 4 mm**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**3.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**215/55 R 17 98 W**
Tyre size FR	**215/55 R 17 98 W**
Tyre size RL	**215/55 R 17 94 V**
Tyre size RR	**215/55 R 17 94 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**258**
Tyre make FR	**258**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**2**		
Number of charging cables (rapid charge)	**1**		

Air vent L, Broken, Replace




Door panel RL, Broken, Replace







Backrest cover RL, Tear, Replace




Service, Maintenance, Check



Air vent R, Broken, Replace




Bumper F, Scratch(es), Repair and paint (complete)








Windscreen, Stone chip(s), Replace





Door FL, Scratch(es), Acceptable




Door RL, Scratch(es), Acceptable




Wing RL, Dent(s) and scratch(es), Acceptable






Alloy rim FL, Scratch(es), Repair and paint (complete)






Alloy rim RL, Scratch(es), Repair and paint (complete)






Step L, Scratch(es), Acceptable




Bumper R, Scratch(es), Repair and paint (complete)







Tailgate / Boot, Dent(s), Acceptable




Boot lid covering R, Scratch(es), Acceptable




Alloy rim RR, Scratch(es), Repair and paint (complete)




Sill trim R, Scratch(es), Repair and paint (complete)




Door FR, Dent(s), Acceptable




Wing RR, Repaired, Check




Door RR, Repaired, Check




Alloy rim FR, Scratch(es), Repair and paint (complete)





Step R, Dent(s), Acceptable




Step R, Scratch(es), Acceptable




Onderhoudshistorie van: WVWZZZ3CZNE075647

ALPHABET

Kenteken	2CGM957
Merk Model	Volkswagen Passat Variant GTE Business 1.4TSi 218pk/cv 5p DSG6
Brandstofsoort	Benzine
Datum deel1	7/15/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
12/1/25	83,271	Inspectie met olieververvanging (vast in	Uitvoeren
12/1/25	83,271	klein materiaal	
12/1/25	83,271	koelwatervloeistof	Bijvullen/-laden
12/1/25	83,271	ruitenwisserrubber achter	Vervangen
12/1/25	83,271	ruitenwisserrubber vooraan	Vervangen
12/1/25	83,271	ruitenwisservloeistof	Bijvullen/-laden
4/25/25	70,053	batterij	Vervangen
4/25/25	70,053	bougie	Vervangen
4/25/25	70,053	klein materiaal	
4/25/25	70,053	koelwatervloeistof	Bijvullen/-laden
4/25/25	70,053	remblokken achter	Vervangen
4/25/25	70,053	remblokken vooraan	Vervangen
4/25/25	70,053	ruitenwisservloeistof	Bijvullen/-laden
4/25/25	70,053	Tussentijds onderhoud (vast interval)	Uitvoeren
4/25/25	70,053	versnellingsbakolie	Vervangen
6/4/24	53,262	Inspectie met olieververvanging (vast in	Uitvoeren
6/4/24	53,262	instelling koplampen	Afstellen
6/4/24	53,262	klein materiaal	
6/4/24	53,262	koelwatervloeistof	Bijvullen/-laden
6/4/24	53,262	luchtfilter interieur	Vervangen
6/4/24	53,262	remvloeistof	Bijvullen/-laden
6/4/24	53,262	ruitenwisserrubber achter	Vervangen
6/4/24	53,262	ruitenwisserrubber vooraan	Vervangen
6/4/24	53,262	ruitenwisservloeistof	Bijvullen/-laden
1/24/24	43,603	controle niveaus	Uitvoeren
1/24/24	43,603	diagnose	Uitvoeren
9/27/23	34,799	klein materiaal	Uitvoeren
9/27/23	34,799	koelwatervloeistof	Bijvullen/-laden
9/27/23	34,799	ruitenwisservloeistof	Bijvullen/-laden
9/27/23	34,799	Tussentijds onderhoud (vast interval)	Uitvoeren
5/31/23	18,981	klein materiaal	
5/31/23	18,981	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
5/31/23	18,981	ruitenwisserrubber achter	Vervangen
5/31/23	18,981	ruitenwisserrubber vooraan	Vervangen