



**Volkswagen ID.4: L521KS**

Vinnumber:	<b>WVGZZE2ZMP000679</b>	Versionname:	<b>ID 4 150kW / 77kWh 1ST Aut</b>
First Registrationdate:	<b>17/06/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>125618</b>	Power Kw:	<b>150</b>
Bodytype:		Body colour:	<b>Mangan Grey metallic</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Electric</b>	Parking lot:	<b>454</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>No</b>		

**Options**

Number of keys total	<b>2</b>	Lining semi-leather
GPS		Lining Alcantara
Autom climate control		Rear parking sensors
Radio multimedia		

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 50 / 20 / 100 / T / Aluminium	5,0 mm	Hankook	Summer
	Right	235 / 50 / 20 / 100 / T / Aluminium	5,0 mm	Hankook	Summer
Rear	Left	235 / 50 / 20 / 100 / T / Aluminium	4,0 mm	Hankook	Summer
	Right	235 / 50 / 20 / 100 / T / Aluminium	4,2 mm	Hankook	Summer

**Assistance equipment**

Number of charging cables (normal)	<b>1</b>
Number of charging cables (rapid charge)	<b>1</b>


**Door FL, Scratch(es), Repair and paint (complete)**



**Door RL, Scratch(es), Polish**



**Wing RL, Scratch(es), Repair and paint (complete)**



**Bumper F, Scratch(es), Repair and paint (complete)**



Bonnet, Chemical pollution, Polish



Windscreen, Stone chip(s), Windscreen repair



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper corner RL, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Bad repair, Repair and paint (complete)



<b>Kenteken</b>	L521KS
<b>Merk Model</b>	Volkswagen ID 4 150kW / 77kWh 1ST Aut.
<b>Brandstofsoort</b>	Elektrisch
<b>Datum deel1</b>	17-06-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
12-02-26	118.379	High Voltage batterij
11-02-26	118.361	Vervanging band
25-06-25	102.050	APK
25-06-25	102.050	Onderhoudsbeurt
25-06-25	102.050	Remvloeistof