

Condition Report / Loss of Value Assessment II



Process

Your order dated

Venue of inspection

Date of inspection

Reference numbers

Vehicle information

Registration no.		Vehicle ident. no.	WAUZZZ4M8SD034890
Type of vehicle	Motor car - Estate	Color / finish	Gray / metallic
Manufacturer	Audi	Next main inspection	12/2027
Type / sales designation	Q7 45 basis TDI quattro	Kilometres read	25,643 km
First registration date	2025-04-09	Emissions class	Euro 6
Gearbox / no. of gears	automatic / 8	Seats / doors	7 / 5
Axles / driven	2 / 2	No. of owners	unknown
Engine	Hybrid / Diesel / electric	Displacement / kW	2,967 ccm / 170 KW
Continuous power		Maximum power	
Charging plug		Battery capacity	

Vehicle information was communicated by the client and verified and supplemented on the vehicle.

Fitted wheels:					
Position	Type of tyre	Type of rim	Manufacturer	Dimensions	Thread depth
front left	winter tyre	alloy wheel	Bridgestone	255/55R19 111H	7 mm
front right	winter tyre	alloy wheel	Bridgestone	255/55R19 111H	7 mm
rear right	winter tyre	alloy wheel	Bridgestone	255/55R19 111H	7 mm
rear left	winter tyre	alloy wheel	Bridgestone	255/55R19 111H	7 mm
Type of spare tyre: Tire Fit					

Common / Condition	
✓ Vehicle is in running order	✗ Underbody check conducted
✗ Vehicle is registered	✓ Main key included (no: 1)
✗ Battery is functioning	Secondary key is stored centrally
✗ Service manual included	
✗ Test drive performed.	
First service not yet due. Remaining mileage 3100 Kilometers.	

Legende : ✓ Yes ✗ No ○ not verifiable ⊗ not included

Repaired previous damage	The previous damage was professionally and correctly rectified	Declaration
Engine hood damaged	yes	
Fender front right damaged	yes	
Door front right damaged	yes	

Remarks
Sommerräder fehlen, Batteriespannung niedrig.
As regards the listed inspection item(s), the possibility of follow-on costs or subsequent damage is not excluded. The result of the inspection is conditional because of the inspection position(s)

Equipment according to VIN query

Standard equipment

airbag passenger side deactivatable	airbag driver side/passenger side
antilock braking system (ABS)	Type of drive: all-wheel drive
Audi Application Store and Smartphone Interface	Audi connect (web-based services)
Audi connect (Emergency and Assistance System)	Audi Drive Select
Audi music interface	exterior mirror vehicle colour
control elements glass look, incl. extended aluminium look	braking system with recovery system, 12,5 V
roof edge spoiler	scuff rails with aluminium insert
Electronic Stability Control (ESP)	electronic stability control (ESC)
first-aid kit / first-aid kit	driver assistance system: start-up assistant (hold-assist)
driver assistance system: brake assistant (Audi pre sense front)	driver assistance system: high-beam assistant
front camera (glass)	driver assistance system: passenger protection system (Audi pre sense basic)
driver assistance system: park assist	parking aid front and rear, acoustic and optical with selective display (APS Plus)
driver assistance system: traffic sign detection	driver assistance system: speed limit display
windshield heat protection glazing	floor mats velours
cargo space partition (net)	cruise control (cruise control)
vehicle speed limiter	automatic transmission - Tiptronic (8-speed)
Shine package	urea tank (SCR) 24 liter
rear lights LED with dynamic flasher	interior equipment decorative trim inserts diamond paint Silver gray
interior equipment interior elements top with contrast seam	interior mirror with automatic dimming
Isofix mounts for child seat	body: 5-door
head airbag system (Sideguard)	lumbar support front, electrically adjustable
steering wheel (sport/leather - 3-spokes) with multiple function and shift function	steering column (steering wheel) mech. height/longitudinal adjustment
light and rain sensor	Mild-hybrid 170 kW (engine 3,0 liter - 170 kW V6 24V TDI)
Mild-Hybrid-Technologie	center armrest front comfort equipment
center differential self-locking	model refinement (2)
multi-media Interface MMI Navigation Plus with MMI Touch	non-smoking package
radio reception digital (DAB)	wheelbase standard
tire repair kit	tire pressure indicator
diesel particulate filter	reversing camera
rear seat backrest split/folding	SCR system (AdBlue technology)
sidebag front	power steering electromechanical
seat occupancy detection for seat belts	seat covers/upholstery: leather / mono.pur 550 combination
sound system DSP / Audi sound system	start/stop system
bumper variant: base	preparation mobile phone with Bluetooth interface
immobilizer (electronic)	heat protection glazing green-tinted (sideways / rear)

Special features

3rd seat row, single seats hinged (2 seats)	adaptive windshield wiper, heated
---	-----------------------------------

Special features

ambient lighting	trailer coupling (ball head electrically pivoted)
Assistance package plus with Remote parking assistant system plus	Assistance package city
driver assistance system: 360 degree all-round protection (Audi pre sense 360°)	driver assistance system: intersection assistant
driver assistance system: egress alert	driver assistance system: intersection assistant rear end
driver assistance system: lane change assistant (Side Assist) incl. Audi pre sense rear	Assistance package Tour
driver assistance system: collision avoidance assistant	driver assistance system: cornering assistant left
driver assistance system: lane-departure warning incl. emergency assistant	driver assistance system: adaptive drive assistant
Assistance package parking with Remote park assist	driver assistance system: parking assistant plus
camera system surround view (Top View)	driver assistance system: manoeuvring assistant
Audi music interface in rear seat area	exterior mirror electrically adjustable, heated + folding, with automatic dimming and Memory
exterior mirror with automatic curb-view tilting, right	Bluetooth hands-free system with voice recognition (Audi Phone Box)
roof liner cloth, black	roof rails black
suspension (adaptive air suspension)	head-up display
Isofix mounts for child seat at passenger seat	instrument cluster digital (virtual cockpit plus)
comfort automatic air-conditioning 4-zone	comfort key with sensor controlled liftgate release incl. (open+close)
loading edge protector (stainless steel)	baggage/cargo space cover electric
fuel tank: 85 liter	light alloy rims 8x19 (5-spoke, star design, for winter tires)
LTE access for Audi Phone Box	Matrix LED headlights
metallic paintwork	styling package black
headlight washer system (headlight washer system)	sidebag front and rear
seats front electrically adjustable (left with Memory)	seat heating front and rear
glazing rear darkened (privacy tinting)	

Condition / damage

side left

door front left edge, scratched, disassemble, grind, polish (Image 22, Image 23)

technology

chassis level regulation, functioning, inspect (Image 20, Image 21)

other

vehicle Battery, discharge, inspect (Image 19)

Inspection conditions

The inspection involved an appraisal of the exterior on the full assembled vehicle which took into account the inspection conditions at the time. No assurance of properties can be given of non-inspected areas or areas that cannot be fully inspected.

This document has an appendix with photo documentation with 23 photos.

Photo appendix



Picture 1



Picture 2

Photo appendix




Picture 3




Picture 4

Photo appendix



Picture 5



Picture 6

Photo appendix



Picture 7



Picture 8

Photo appendix



Picture 9



Picture 10

Photo appendix



Picture 11



Picture 12

Photo appendix



Picture 13




Picture 14

Photo appendix



Picture 15



Picture 16

Photo appendix



Picture 17



Picture 18

Photo appendix



Picture 19 vehicle, Battery, discharge, inspect



Picture 20 chassis, level regulation, functioning, inspect

Photo appendix




Picture 21 chassis, level regulation, functioning, inspect



Picture 22 door front left, edge, scratched, disassemble, grind, polish

Photo appendix



Picture 23 door front left, edge, scratched, disassemble, grind, polish