



**Volkswagen Taigo: S604ND**

Vinnnumber:	<b>WVGZZZCSZPY054091</b>	Versionname:	<b>Taigo 1.0 TSI 70kW Life</b>
First Registrationdate:	<b>13/03/2023</b>	Fiscalpower:	
Expertise Mileage:	<b>136111</b>	Power Kw:	<b>70</b>
Bodytype:		Body colour:	<b>Deep Black Pearl</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Parking lot:	<b>797</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>Yes</b>		

**Options**

Number of keys total	<b>2</b>	Rear parking sensors
Manual climate control		
Radio multimedia		

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 60 / 16 / 92 / V / Aluminium	3,0 mm	Goodyear	Summer
	Right	205 / 60 / 16 / 92 / V / Aluminium	2,8 mm	Goodyear	Summer
Rear	Left	205 / 60 / 16 / 92 / V / Aluminium	6,0 mm	Continental	Summer
	Right	205 / 60 / 16 / 92 / V / Aluminium	5,5 mm	Continental	Summer

**Assistance equipment**

Number of charging cables (rapid charge)	<b>0</b>
--	----------

**Interior, Dirty, Cleaning**



**Service, Maintenance, Execute**



**Outside rear-view mirror housing L, Scratch(es), Replace and paint**



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Polish



Door FR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



<b>Kenteken</b>	S604ND
<b>Merk Model</b>	Volkswagen Taigo 1.0 TSI 70kW Life
<b>Brandstofsoort</b>	Benzine
<b>Datum deel1</b>	13-03-23

Datum reparatie	Kilometerstand	Reparatie omschrijving
27-10-25	108.084	Bougie
27-10-25	108.084	Koolstoffilter
27-10-25	108.084	Onderhoudsbeurt
27-10-25	108.084	Remschijf + blokken voor
27-10-25	108.084	Ruitenwischerblad(en) voorzijde
27-10-25	108.084	Vervanging band
24-02-25	88.221	Luchtfilter
24-02-25	88.221	Onderhoudsbeurt
24-02-25	88.221	Remvloeistof
24-02-25	88.221	Ruitenwischerblad(en) voorzijde
24-02-25	88.221	Vervanging band
20-06-24	60.407	Bougie
20-06-24	60.407	Onderhoudsbeurt
20-06-24	60.407	Remblokken voorzijde
20-06-24	60.407	Ruitenwischerblad(en) achterzijde
20-06-24	60.407	Ruitenwischerblad(en) voorzijde
06-11-23	28.053	Onderhoudsbeurt