



RENAULT KANGOO FURGÓN L1 1.5 Blue dCi Furgón derivado de turismo 70KW (95CV) 4P manual: 5982-MCS

Vinnumber:	VF1RFK00770152240	Versionname:	
First Registrationdate:	9/12/2022	Fiscalpower:	0
Expertise Mileage:	101548	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Radio:	
Number keys remote:	2	Rear parking sensors:	
Windows electric F:			
Cruise Control:			
Steering wheel multifunctional:			
Type of climate control:	Manual climate control		

Tyres

195/65/15/95 H				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL:				4.0
Tyre profile depth FR:				4.0
Tyre profile depth RL:				4.0
Tyre profile depth RR:				4.0
Tyre size FL:				195/65 R 15 95 H
Tyre size FR:				195/65 R 15 95 H
Tyre size RL:				195/65 R 15 95 H
Tyre size RR:				195/65 R 15 95 H
Tyre type FL:				Summer
Tyre type FR:				Summer
Tyre type RL:				Summer
Tyre type RR:				Summer
Tyre make FL:				259
Tyre make FR:				259
Tyre make RL:				259
Tyre make RR:				259

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
--------------	------------	-------	------------

Interior, Damaged, Repair and paint (complete)





Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Paint



Outside rear-view mirror housing L, Scratch(es), Paint



Wing FL, Scratch(es), Paint



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Paint



Door FR, Scratch(es), Paint



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Paint



Boot door panel RR, Scratch(es), Paint



Tyres, No damage, Check

