



FIAT TALENTO: 2BDD557

Vinnumber:	ZFAFFL002M5175313	Versionname:	
First Registrationdate:	7/10/2021	Fiscalpower:	
Expertise Mileage:	196108	Power Kw:	
Bodytype:		Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:	Front		
Fueltype:	Diesel		
Maintenance:	NOT OK		
Maintenance:	onderhoud nu		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	1	Central consol F
Number keys remote:	1	Rear parking sensors
Windows electric F:		Sliding door right-side
Board Computer:		
Cruise Control:		
Steering wheel multifunctional:		
Type of headlighting:	Headlighting Halogen	
Type of GPS:	GPS big screen color	
Type of Lining:	Lining fabrics	
Type of climate control:	Manual climate control	
Type of radio:	Multimedia	
Type of GPS storage:	HD	

Tyres

205/65/16/107 T				
Summer tyres:	Fr.L.	Hankook: 8 mm	Fr.R.	Hankook: 8 mm
	Re.L.	Other: 6 mm	Re.R.	Other: 5 mm
Tyre profile depth FL				8.0
Tyre profile depth FR				8.0
Tyre profile depth RL				6.0
Tyre profile depth RR				5.0
Tyre size FL				205/65 R 16 107 T
Tyre size FR				205/65 R 16 107 T
Tyre size RL				205/65 R 16 107 T
Tyre size RR				205/65 R 16 107 T
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				263
Tyre make RR				263

Assistance equipment

Spare wheel:	Yes	Jack	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		



Ignition key, Missing, Replace



Dashboard, Hole, Smart repair



Floor covering FL, Damaged, Smart repair



Seat cover FL, Worn, Acceptable



Bumper F, Scratch(es), Acceptable



Wing RL, Dent(s), Paintless dent repair



Door seal FL, Broken, Replace



Wheel aperture RL, Dent(s) and scratch(es), Spot repair



Wheel aperture RR, Dent(s) and scratch(es), Spot repair



Boot door panel RL, Dent(s), Paintless dent repair



Bumper moulding R, Dent(s) and scratch(es), Replace and paint



Boot door panel RR, Dent(s), Acceptable



Bumper R, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Acceptable



Door RR, Dent(s), Paintless dent repair



Door seal RR, Broken, Replace



Wing RR, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Bodywork, Not original part, Sticker removal

