



Volkswagen Tiguan: R680RG

Vinnnumber:	WVGZZZ5NXPW404044	Versionname:	Tiguan 1.4 TSI PHEV 180kW R-Line Business+ DSG-6
First Registrationdate:	2/11/2022	Fiscalpower:	6
Expertise Mileage:	156804	Power Kw:	110
Bodytype:		Body colour:	Dolphin Grey metallic
Gearbox:	Automatic	Paint type:	Metallic
Transmission:		Type of rims (mounted):	Aluminium
Fueltype:	Hybrid Petrol	Parking lot:	407
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Lining semi-leather
GPS		Lining Alcantara
Autom climate control		Sun Roof electric
Radio multimedia		Panoramic roof
		Rear parking sensors
		Hook

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	255 / 45 / 19 / 104 / V / Aluminium	6,0 mm	Vredestein	Summer
	Right	255 / 45 / 19 / 104 / V / Aluminium	6,0 mm	Vredestein	Summer
Rear	Left	255 / 45 / 19 / 104 / V / Aluminium	4,2 mm	Continental	Summer
	Right	255 / 45 / 19 / 104 / V / Aluminium	4,6 mm	Continental	Summer

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Interior, Dirty, Cleaning



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Bumper F, Stone chip(s), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Kenteken	R680RG
Merk Model	Volkswagen Tiguan 1.4 TSI PHEV 180kW R-Line Business+ DSG-6
Brandstofsoort	Benzine
Datum deel1	02-11-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
31-03-26	153.206	Onderhoudsbeurt
31-03-26	153.206	Remschijf + blokken achter
31-03-26	153.206	Sleutelbatterij
19-02-26	150.312	Reparatie band(en)
29-10-25	142.627	Airo vulling
29-10-25	142.627	Luchtfilter
29-10-25	142.627	Onderhoudsbeurt
29-10-25	142.627	Ruitenwischerblad(en) achterzijde
29-10-25	142.627	Ruitenwischerblad(en) voorzijde
29-10-25	142.627	Vervanging band
02-07-25	128.759	Bougie
02-07-25	128.759	Onderhoudsbeurt
02-07-25	128.759	Vervanging band
12-02-25	108.708	Onderhoudsbeurt
12-02-25	108.708	Remblokken voorzijde
27-11-24	100.833	Onderhoudsbeurt
27-11-24	100.833	Ruitenwischerblad(en) achterzijde
27-11-24	100.833	Ruitenwischerblad(en) voorzijde
19-08-24	85.125	Luchtfilter
19-08-24	85.125	Onderhoudsbeurt
19-08-24	85.125	Remklaw(en) achterzijde
19-08-24	85.125	Remvloeistof
19-08-24	85.125	Sleutelbatterij
19-08-24	85.125	Uitlijnen voor en achterwielen
05-08-24	83.353	Vervanging band
29-04-24	72.392	Bougie
29-04-24	72.392	Luchtfilter
29-04-24	72.392	Onderhoudsbeurt
29-04-24	72.392	Ruitenwischerblad(en) achterzijde
29-04-24	72.392	Ruitenwischerblad(en) voorzijde
24-01-24	60.237	Vervanging band
07-12-23	52.446	Onderhoudsbeurt
02-08-23	34.026	Onderhoudsbeurt
02-08-23	34.026	Ruitenwischerblad(en) voorzijde
16-05-23	23.316	Uitlijnen voor en achterwielen
31-03-23	18.558	Onderhoudsbeurt