MACADAM








BMW 3 Reeks (KKL): 2FBY475

Vinnumber:	**WBA18FS0808E33225**	Versionname:	**320e (G20) 2.0i 204pk/cv 4p Aut.**
First Registrationdate:	**20/03/2024**	Fiscalpower:	
Expertise Mileage:	**111182**	Power Kw:	**120**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Plug-in Hybrid Petrol**		
Maintenance	**OK**		
Maintenance	**31/12/2027**		
Maintenance	**19000 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Type of Tow bar	**Tow bar collapsible**
GPS			
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Winter tyres:	**225/50/17/98 H**			
	Fr.L.	**Goodyear: 7 mm**	Fr.R.	**Goodyear: 7 mm**
	Re.L.	**Goodyear: 4 mm**	Re.R.	**Goodyear: 4 mm**

Tyre profile depth FL	**7.0**
Tyre profile depth FR	**7.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**225/50 R 17 98 H**
Tyre size FR	**225/50 R 17 98 H**
Tyre size RL	**225/50 R 17 98 H**
Tyre size RR	**225/50 R 17 98 H**
Tyre type FL	**Winter**
Tyre type FR	**Winter**
Tyre type RL	**Winter**
Tyre type RR	**Winter**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**1**

Ignition key, Not functioning (well), Acceptable



Seat cover FL, Scratch(es), Acceptable




Door panel RL, Scratch(es), Replace











Bonnet, Hail damage, Forfeit hail (heavy)



Bumper F, Scratch(es), Acceptable




Bonnet, Scratch(es), Acceptable




Wing FL, Scratch(es), Acceptable





Door FL, Scratch(es), Acceptable





Outer door handle FL, Scratch(es), Acceptable




Roof pillar L, Dent(s) and scratch(es), Acceptable






Charging cable (normal), Missing, Check



Bumper R, Deformed / Strained, Repair and paint (complete)





Tailgate / Boot, Scratch(es), Acceptable





Wing RR, Dent(s) and scratch(es), Repair and paint (complete)







Door FR, Dent(s), Acceptable




Bodywork, Paint measurement, Acceptable



Roof, Hail damage, Forfeit hail (heavy)




Roof, Scratch(es), Acceptable






Onderhoudshistorie van: WBA18FS0808E33225

ALPHABET

Kenteken	2FBY475
Merk Model	BMW 320e (G20) 2.0i 204pk/cv 4p Aut.
Brandstofsoort	Benzine
Datum deel1	3/20/24

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
12/8/25	96,341	BMW/MINI service standaard omvang	Uitvoeren
12/8/25	96,341	klein materiaal	
12/8/25	96,341	ruitenwisserrubber vooraan	Vervangen
12/8/25	96,341	ruitenwisservloeistof	Bijvullen/-laden
12/8/25	96,341	service microfilter	Uitvoeren
12/8/25	96,341	service motorolie	Uitvoeren
6/24/25	65,220	BMW/MINI service standaard omvang	Uitvoeren
6/24/25	65,220	BMW/MINI service voertuig-check	Uitvoeren
6/24/25	65,220	bougie	Vervangen
6/24/25	65,220	klein materiaal	
6/24/25	65,220	ruitenwisservloeistof	Bijvullen/-laden
6/24/25	65,220	service luchtfilter	Uitvoeren
6/24/25	65,220	service microfilter	Uitvoeren
6/24/25	65,220	service motorolie	Uitvoeren
12/16/24	31,965	BMW/MINI service standaard omvang	Uitvoeren
12/16/24	31,965	BMW/MINI voertuigcontrole	Uitvoeren
12/16/24	31,965	controle niveaus	Uitvoeren
12/16/24	31,965	klein materiaal	
12/16/24	31,965	service microfilter	Uitvoeren
12/16/24	31,965	service motorolie	Uitvoeren