



Hyundai Santa Fe: [Redacted]

Vinnnumber:	KMHS4812DNU040034	Versionname:	
First Registrationdate:	26/04/2022	Fiscalpower:	
Expertise Mileage:	104392	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3312
Fueltype:	Hybrid Petrol		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Sun Roof electric:	
Seats F heated:		Panoramic roof:	
Radio multimedia:		Front parking sensors:	
Type of headlighting:	Headlighting LED	Rear parking sensors:	
Type of GPS:	GPS big screen color	Type of Tow bar:	Tow bar removable
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		
Head-up Display:			
Sport seats:			
Type of GPS storage:	HD		

Limited Technical Inspection

Tyres

235/55/19/105 V				
Summer tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				235/55 R 19 105 V
Tyre size FR				235/55 R 19 105 V
Tyre size RL				235/55 R 19 105 V
Tyre size RR				235/55 R 19 105 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				265
Tyre make FR				265
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Emergency spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	1		
Number of charging cables (rapid charge):	0		

Total cost ex VAT: 2499,08

Floor covering FL, Damaged, Replace: 624,97



Engine insulation, Damaged, Replace 0,00



Windscreen, Crack, Replace 0,00



Charging cable (fast), Missing, Replace 256,50



Luggage compartment cover, Missing, Replace 1103,26



Bumper R, Scratch(es), Spot repair 148,33



Step R, Scratch(es), Acceptable 0,00



Door RR, Dent(s), Acceptable 0,00



Door trim RR, Scratch(es), Repair and paint (complete) 161,81



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21



Door FR, Scratch(es), Acceptable 0,00

