MACADAM








RENAULT Megane: 3438-MGY

Vinnumber:	**VF1RFB00970681446**	Versionname:	**Equilibre TCe 103 kW (140CV) GPF berlina con portón 103kW 5P manual**
First Registrationdate:	**23/05/2023**	Fiscalpower:	
Expertise Mileage:	**153520**	Power Kw:	
Bodytype:	**Berline**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Type of rims (mounted)	**Steel**
Transmission:			
Fueltype:	**Petrol**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**No**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**No**		

Options

Number of keys total	**2**	Central consol F	
Number keys remote	**2**	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Radio multimedia			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**205/55/16/91 V**			
	Fr.L.	**Goodyear: 3 mm**	Fr.R.	**Goodyear: 3 mm**
	Re.L.	**Goodyear: 6 mm**	Re.R.	**Goodyear: 6 mm**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**3.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**6.0**
Tyre size FL	**205/55 R 16 91 V**
Tyre size FR	**205/55 R 16 91 V**
Tyre size RL	**205/55 R 16 91 V**
Tyre size RR	**205/55 R 16 91 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

MOT certificate, Missing, Repair/replace (lump sum)




Registration document, Missing, Repair/replace (lump sum)




Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)




Bumper F, Scratch(es), Repair and paint (complete)





Bonnet, Hail damage, Paintless dent repair (hail)




Wing FR, Scratch(es), Repair and paint (complete)




Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Repair and paint (complete)





Tyres, No damage, Check











Roof, Hail damage, Repair and paint (complete)




ALPHABET

Datos del vehículo

Marca	RENAULT	Matrícula	3438-MGY
Modelo	Mégane	VIN	VF1RFB00970681446
Versión	Equilibre TCe 103 kW (140CV) GPF berlina con portón 103kW 5P manual		

Histórico

Fecha	Descripción	Kilómetros	Taller
13/12/2023	Rev. 30.000 kms	30525	TALLER MECANICO TURIEL S.L.
31/01/2024	Luna parabrisas	37037	RALARSA HOLDING S.L.
11/07/2024	Rev. 60.000 kms	60899	TALLER MECANICO TURIEL S.L.
22/11/2024	Escobillas Limpiaparabrisas, varios	72655	TALLER MECANICO TURIEL S.L.
27/03/2025	, Luna parabrisas	87865	RALARSA HOLDING S.L.
09/05/2025	Aceite motor - - - ALP EURO, Arandela / tapón cárter, Filtro aceite, Filtro antipolen - MANN-FILTER - Rec.Plat. EuroTaller - Nueva, Rellenar niveles, Serv inspección 90000 KM, Sustituir Filtro antipolen, Sustituir Rellenar niveles, Tasa de gestión de aceites usados	93163	TALLER MECANICO TURIEL S.L.
21/05/2025	Verificar Diagnosis	94805	RENOVADOS VELASCO S.A.
20/05/2025	Alineado sencillo, Ecotasa - N2, Goodyear / 542449 205/55X16 GYEAR.EFIG.PERF2 91V, Sustitucion y kit de montaje	94805	RENOVADOS VELASCO S.A.
29/01/2026	Aceite motor - - - ALP EURO, Bujía - DENSO - Rec.Plat. EuroTaller, Filtro aceite - BOSCH - Rec.Plat. EuroTaller, Filtro aire - BOSCH - Rec.Plat. EuroTaller, Líquido frenos - DOT4 OEM1 - Nueva, Serv inspección 120000 KM, Sustituir Bujía, Sustituir Filtro aire, Sustituir Líquido frenos, Tasa de gestión de aceites usados	123627	TALLER MECANICO TURIEL S.L.
27/07/2026	Aleta trasera izquierda	135346	Sayago Motor, S.L.U.
04/09/2026	Luna parabrisas	151543	RALARSA HOLDING S.L.

Fecha	Descripción	Kilómetros	Taller