



RENAULT KANGOO EXPRESS: FC-820-LF

Vinnumber:	VF1FWEZBC61367469	Versionname:	RENAULT KANGOO EXPRESS Z.E. 33 Grand Confort VU [3P] bva 1-60CH-7cv (fourgonnettesimple cabine)
First Registrationdate:	12/12/2018	Fiscalpower:	
Expertise Mileage:	46789	Power Kw:	44
Bodytype:	Transporter	Body colour:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Electric	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
Windows electric F		Sliding door right-side	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			
Type of climate control	Autom climate control		

Tyres

	195/65/15/95 H			
Summer tyres:	Fr.L.	Cooper: 20%	Fr.R.	Cooper: 15%
	Re.L.	Cooper: 15%	Re.R.	Cooper: 20%
Tyre profile depth FL				6.8
Tyre profile depth FR				7.2
Tyre profile depth RL				7.2
Tyre profile depth RR				7.0
Tyre size FL				195/65 R 15 95 H
Tyre size FR				195/65 R 15 95 H
Tyre size RL				195/65 R 15 95 H
Tyre size RR				195/65 R 15 95 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				1957075
Tyre make FR				1957075
Tyre make RL				1957075
Tyre make RR				1957075

Assistance equipment

Spare wheel	Yes	Jack	Yes
Interior, Stain, Cleaning			





Remote ignition key, Missing, Repair/replace (lump sum)



Wheel cover FR, Broken, Replace



Wheel cover RR, Broken, Replace




Wheel cover FL, Broken, Replace



Door FL, Dent(s), Repair and paint (complete)



Side wall RL, Scratch(es), Polish



Door trim FL, Scratch(es), Replace



Bumper F, Scratch(es), Acceptable



Sliding door R, Scratch(es), Polish



Door FR, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Replace



Roof pillar R, Dent(s), Acceptable




Bumper R, Deformed / Strained, Repair and paint (complete)



Boot door panel RL, Dent(s), Repair and paint (complete)



Boot door panel RR, Dent(s) and scratch(es), Acceptable



Boot door lining L, Broken, Replace



Charging cable (normal), Missing, Replace



Bodywork, Not original part, Sticker removal small



Load compartment roof, Dent(s), Repair and paint (complete)





Historique Maintenance

Immatriculation: **FC-820-LF** Date de 1ère immatriculation: **12/12/2018**

Modèle: **Renault KANGOO EXPRESS Z.E. 33 Grand Confort VU [3P] bva 1-60CH-7cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
13/06/2025	33.806	FAURIE AUTO MONTAUBAN	RECYCLAGE
	0		BALAIS ESSUIE GLACE AV
	0		REVISION
	0		LIQUIDE DE REFROIDISSEMENT RPLT
21/03/2025	31.314	AUTO CONTROLE 82	CONTROLE TECHNIQUE
12/06/2023	24.290	FAURIE AUTO MONTAUBAN	RECYCLAGE
	0		BALAIS ESSUIE GLACE AV
	0		REVISION
	0		BATTERIE RPLT
	0		LIQUIDE DE FREIN
	0		FILTRE CLIM RPLT
24/03/2021	13.678	FAURIE AUTO MONTAUBAN	REVISION
	0		BALAIS ESSUIE GLACE AV
	0		FILTRE CLIM RPLT