MACADAM









CITRO?N BERLINGO: FC-591-LF

Vinnumber:	**VF77DBHW6JN528573**	Versionname:	**CITRO?N BERLINGO BlueHDi 75 BVM Club M VU [3P] bvm 5-75CH-5cv (fourgonnette-)**
First Registrationdate:	**12/12/2018**	Fiscalpower:	
Expertise Mileage:	**208237**	Power Kw:	**55**
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 5 VIT**	Paint type	**Opaque**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**3**		
Number of seats	**3**		
Number head rests	**3**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**2**	Tow bar	
Number keys remote	**1**	Radio	
Windows electric F		Rear parking sensors	
Cruise Control		Sliding door right-side	
Type of climate control	**Manual climate control**	Seat cover lining	**Lining Other**

Tyres

Summer tyres:	**195/70/15/104 R**			
	Fr.L.	**Hankook: 20%**	Fr.R.	**Hankook: 20%**
	Re.L.	**Michelin: 80%**	Re.R.	**Michelin: 90%**

Tyre profile depth FL	**7.0**
Tyre profile depth FR	**6.8**
Tyre profile depth RL	**2.8**
Tyre profile depth RR	**2.0**
Tyre size FL	**195/70 R 15 104 R**
Tyre size FR	**195/70 R 15 104 R**
Tyre size RL	**195/70 R 15 104 R**
Tyre size RR	**195/70 R 15 104 R**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**260**
Tyre make FR	**260**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Spare wheel	**Yes**

Seat cover FL, Not original part, Acceptable




Steering wheel, Worn, Repair/replace (lump sum)



Seat cover FR, Not original part, Acceptable




Interior, Stain, Cleaning



Centre console, Hole, Repair/replace (lump sum)



Tyre RL, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Paint





Door trim FL, Scratch(es), Replace






Side panel L, Stone chip(s), Paint




Bumper F, Scratch(es), Repair and paint (complete)








Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)




Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)





Outside rear-view mirror base R, Broken, Replace and paint




Outside rear-view mirror housing R, Scratch(es), Replace





Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)





Bumper R, Deformed / Strained, Repair and paint (complete)




Bodywork, Not original part, Sticker removal small




ALPHABET

Historique Maintenance

Immatriculation: **FC-591-LF** Date de 1ère immatriculation: **12/12/2018**

Modèle: **Citroen BERLINGO BlueHDi 75 BVM Club M VU [3P] bvm 5-75CH-5cv (fourgonnette-)**

Date	Kilométrage	Fournisseur	Descriptif
04/11/2026	199.357	NOUVELLE SOCIETE FAM	VIDANGE BOITE DE VITESSE ET FILTRE
07/05/2026	193.159	NOUVELLE SOCIETE FAM	LAMPE AR RPLT
25/11/2025	180.868	NOUVELLE SOCIETE FAM	DIAG
			SOUFFLET DE CARDAN RPLT
			DIVERS
29/10/2025	178.908	NOUVELLE SOCIETE FAM	DISQUES PLAQUETTES AV RPLT
			KIT ACCESSOIRES RPLT
			KIT DISTRIBUTION RPLT
			BALAIS ESSUIE GLACE AV
			REVISION ET CLIM
16/01/2025	155.653		LAMPE CODE AVD RPLT
26/12/2024	153.986	NOUVELLE SOCIETE FAM	REVISION ET CLIM ET AIR ET CARBURANT
23/10/2024	149.809	NOUVELLE SOCIETE FAM	DIAG
			DIVERS
24/05/2024	135.542		DIAG
			DIVERS ECHAPPEMENT
05/03/2024	129.655		REVISION
			AMORTISSEURS AV RPLT
			PLAQUETTES AV RPLT
			PLAQUETTES AR RPLT
			DIVERS ELEC
22/01/2024	125.951		BATTERIE RPLT
18/01/2024	125.150		ECLAIRAGE DE PLAQUE RPLT
			LAMPE RPLT
10/10/2023	118.000		BALAIS ESSUIE GLACE AV
24/03/2023	104.471		LIQUIDE DE FREIN
			DIVERS ECHAPPEMENT
			DIVERS CLIM
			REVISION ET CLIM ET AIR ET CARBURANT
16/03/2022	79.493		ADBLUE
			PLAQUETTES AR RPLT
			REVISION ET CLIM

Historique Maintenance

Immatriculation: **FC-591-LF** Date de 1ère immatriculation: **12/12/2018**

Modèle: **Citroen BERLINGO BlueHDi 75 BVM Club M VU [3P] bvm 5-75CH-5cv (fourgonnette-)**

Date	Kilométrage	Fournisseur	Descriptif
02/02/2022	76.425		SUPPORT MOTEUR RPLT
29/04/2021	55.173		REVISION ET CLIM ET AIR ET CARBURANT
			DISQUES PLAQUETTES AV RPLT
			LIQUIDE DE FREIN
			ADBLUE
08/12/2020	25.542		LAMPE CODE AVD RPLT
21/08/2020	25.542		REVISION ET CLIM
			LIQUIDE DE FREIN
			ADBLUE
19/07/2019	10.731		APPOINT D HUILE