

Vehicle details

VIN	5YJSA7E21 JF288378	Brand	TESLA	Maintenance date	-
Licence Plate		Model	Model S 75 kWh All-Wheel Drive 5d Spec88	Maintenance mileage	-
Registration date	27/12/2018	Year	2018	Exterior Color	Black Solid
Odometer	213 901 km	Engine size	-	interior Color	Black
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	21/07/2026	Inspection loc.	
-----------------	------------	-----------------	--



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Central locking	✓
Electric windows	✓
4x4	✓
Mixed upholstery	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 245/45/19 Summer 3.0 mm



Pirelli 245/45/19 Summer 3.0 mm



Pirelli 245/45/19 Summer 8.0 mm

Pirelli 245/45/19 Summer 8.0 mm

Exterior

5




Part	Tailgate / Boot door
Position	-
Damages	Scratched
Severity	-
Repair mode	Repair

6



Part	Wing
Position	Back right
Damages	Dented
Severity	-
Repair mode	Repair

7



Part	Roof post A/B/C
Position	Right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

8



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

9



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

1



Part	Other interior
Position	Front left
Damages	Worn out
Severity	-
Repair mode	For info stoelwang leer

2



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

3



Part	Other interior
Position	Front left
Damages	Worn out
Severity	-
Repair mode	For info b stijl bekleding

4



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning