



Mercedes C: 2BRL724

Vinnumber:	W1K2062031F048601	Versionname:	
First Registrationdate:	24/02/2022	Fiscalpower:	
Expertise Mileage:	158016	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front		
Fueltype:	Hybrid Diesel		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Central consol F	
Number keys remote	2	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Roof bar black	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Steering wheel leather			
Seats F heated			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Type of radio	Multimedia		
Type of GPS storage	HD		

Tyres

	205/55/17/91 V			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 17 91 V
Tyre size FR				205/55 R 17 91 V
Tyre size RL				205/55 R 17 91 V
Tyre size RR				205/55 R 17 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT

1083,34

Bumper F, Scratch(es), Repair and paint (complete)	232,99
--	--------



Alloy rim RR, Scratch(es), Acceptable	0,00
---------------------------------------	------



Alloy rim FR, Scratch(es), Repair and paint (complete)	161,12
--	--------



Wing RR, Scratch(es), Repair and paint (complete)	339,03
---	--------



Door RR, Scratch(es), Repair and paint (complete)	350,20
---	--------

