



Skoda Superb:

Vinnumber:	TMBJH7NP5N7050872	Versionname:	
First Registrationdate:	22/06/2022	Fiscalpower:	
Expertise Mileage:	156129	Power Kw:	
Bodytype:		Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2422
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Luggage cover:	
Steering wheel multifunctional:		Front parking sensors:	
Seats F heated:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Tyres

215/55/17/92 H				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/55 R 17 92 H
Tyre size FR				215/55 R 17 92 H
Tyre size RL				215/55 R 17 92 H
Tyre size RR				215/55 R 17 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	2579,21
Seat cover FL, Stain, Cleaning	29,16




Seat cover FR, Stain, Cleaning 29,16



Bumper F, Scratch(es), Repair and paint (complete) 355,89




Bonnet, Scratch(es), Acceptable 0,00



Wing RL, Dent(s) and scratch(es), Repair and paint (complete) 577,40




Outer door handle RL, Scratch(es), Repair and paint (complete) 161,81




Door FL, Dent(s) and scratch(es), Repair and paint (complete) 534,95



Bumper R, Scratch(es), Repair and paint (complete) 355,89



Rear window, Scratch(es), Acceptable 0,00



Door RR, Dent(s) and scratch(es), Repair and paint (complete) 534,95



Wing RR, Dent(s), Acceptable

0,00



Roof, Chemical polution, Polish

0,00

