




## 2-EDQ-057

2-EDQ-057 · Acenta L1H1 DIG-T 130 MT · 3 June 2026 · Zaventem (BE)

### Specifications

License Plate Number	2-EDQ-057	Fuel Type	Gasoline
Manufacturer	NISSAN	VIN	VNVNFK00671445809
Model	Townstar	Cylinder Capacity	1.332 <sup>cm<sup>3</sup></sup>
Model Versions	Acenta L1H1 DIG-T 130 MT	Transmission Type	Handmatig geschakelde transmissie
Body Type	VAN	First Admission	07-09-2023
Color	White	Odometer	38.773 <sup>Km</sup>
Paint Type	Matte	Numer Of Keys	2
Production Year	2023	Interior	Grey
KW	96	Number Headrests	2

Images





## Accessories

ABS

Airbags

Audio System

Bluetooth car kit

Central door locking

Cruise control

Electric windows front

Electrically adjustable exterior mirrors

Floor plate

Manual air conditioning

Rear parking sensors

Steering wheel multifunction

## Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

## Tire Specifications

<b>Tire</b>	<b>Profile</b>	<b>Brand</b>	<b>Width</b>	<b>Aspect Ratio</b>	<b>Radial</b>	<b>Type</b>
Front Left	3 <sup>mm</sup>	Delinte	205 <sup>mm</sup>	60 <sup>mm</sup>	16 <sup>inch</sup>	Summer
Rear Left	4 <sup>mm</sup>	Continental	205 <sup>mm</sup>	60 <sup>mm</sup>	16 <sup>inch</sup>	Summer
Front Right	3 <sup>mm</sup>	Delinte	205 <sup>mm</sup>	60 <sup>mm</sup>	16 <sup>inch</sup>	Summer
Rear Right	4 <sup>mm</sup>	Continental	205 <sup>mm</sup>	60 <sup>mm</sup>	16 <sup>inch</sup>	Summer
Spare Tire Type	Fully Fledged					
Spare Tire Profile	4 <sup>mm</sup>					

## Damages



Damage Part

Hood



Damage Type

Stonechipping

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Wheelcover - Right Front



Damage Type

Missing

Repair Type

Replace

Acceptable

No



Damage Part

Roof



Damage Type

Small scratch(es)

Repair Type

Polish

Acceptable

No



Damage Part

Interior



Damage Type

Stains & dirt

Repair Type

Cleaning

Acceptable

No