SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-FBA-715

2-FBA-715 · ST Line X 1.0i EcoBoost 155pk - 114kW - Mhev A7 -Clipper · 27 October 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FBA-715
Manufacturer	FORD
Model	Focus
Model Versions	ST Line X 1.0i EcoBoost 155pk - 114kW - Mhev A7 -Clipper
Body Type	5 door hatchback
Color	Grey
Paint Type	Metallic
Production Year	2024
KW	114

Fuel Type	Hybrid Gasoline
VIN	WF0PXXGCHPRB65562
Cylinder Capacity	999 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	12-03-2024
Odometer	98.041 Km
Numer Of Keys	2
Interior	Black
Number Headrests	5

Images




























WSeasonExpert



UNIROYAL

Accessories

ABS	Electrically adjustable exterior mirrors
Airbags	Front & rear parking sensors
Alloy wheels	Leather steering wheel
Audio System	Navigation system
Automatic air conditioning	Rear view camera
Bluetooth car kit	Roller cover / parcel shelf
Central door locking	Seat heating
Centre armrest	Steering wheel multifunction
Cruise control	Steeringwheel – Heated
Electric rear windows	Windscreen – Heated
Electric windows front	

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 mm	Uniroyal	215 mm	50 mm	17 inch	All Season
Rear Left	4 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Front Right	6 mm	Uniroyal	215 mm	50 mm	17 inch	All Season
Rear Right	4 mm	Uniroyal	215 mm	50 mm	17 inch	All Season
Spare Tire Type	None					

Damages





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Small dent(s)	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Small dent(s)	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Left	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Front	Damaged	Rim repair	No





Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Right	Small scratch(es)	Polish	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Frontdoor – Right	Small scratch(es)	Deurgreep	Touch-up / Polish	No




Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Rear	Damaged	Rim repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	small dents / small scratches	Panelbeating & Spray	No






Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No