



Mercedes A-Klasse (UKL): 2AGG436

Vinnumber:	W1K1770821V102593	Versionname:	A160 Business Solution 1.3i 109pk/cv 5p
First Registrationdate:	25/03/2021	Fiscalpower:	
Expertise Mileage:	105827	Power Kw:	80
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	NOT OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	No Tow bar
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/45/17/94 Y			
Summer tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 2 mm	Re.R.	Pirelli: 2 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				2.0
Tyre profile depth RR				2.0
Tyre size FL				225/45 R 17 94 Y
Tyre size FR				225/45 R 17 94 Y
Tyre size RL				225/45 R 17 94 Y
Tyre size RR				205/60 R 16 92 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Service, Maintenance, Check			



Seat cover R, Stain, Cleaning




Seat cover FL, Stain, Cleaning




Bumper F, Scratch(es), Repair and paint (complete)




Alloy rim RL polished, Rust, Acceptable




Outside rear-view mirror housing L, Scratch(es), Acceptable




Alloy rim FL polished, Rust, Acceptable



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Wing RR, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Acceptable



Kenteken	2AGG436
Merk Model	Mercedes A160 Business Solution 1.3i 109pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	3/25/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
11/23/25	86,564	accu	Vervangen
10/9/25	83,585	klein materiaal	
10/9/25	83,585	remblokken achter	Vervangen
10/9/25	83,585	remblokken vooraan	Vervangen
7/29/25	78,402	batterij	Vervangen
7/29/25	78,402	klein materiaal	
7/29/25	78,402	mercedes assyst b	Uitvoeren
7/29/25	78,402	remvloeistof	Vervangen
7/29/25	78,402	ruitenswisserrubber achter	Vervangen
7/29/25	78,402	ruitenswisserrubber vooraan	Vervangen
2/4/25	69,687	gordelspanner	Vervangen
2/4/25	69,687	klein materiaal	
6/6/24	61,207	bougie	Vervangen
6/6/24	61,207	klein materiaal	
6/6/24	61,207	luchtfilter	Vervangen
6/6/24	61,207	mercedes assyst a	Uitvoeren
6/6/24	61,207	ruitenswisserrubber vooraan	Vervangen
5/25/23	41,385	klein materiaal	
5/25/23	41,385	mercedes assyst b	Uitvoeren
5/25/23	41,385	remvloeistof	Vervangen
4/26/22	19,385	klein materiaal	Uitvoeren
4/26/22	19,385	mercedes assyst a	Uitvoeren