



Ford Mustang: L950JX

Vinnumber:	WF0TK1EMXMA16259	Versionname:	Mustang Mach-E 190kW/ 75,7kWh RWD automaat
First Registrationdate:	6/07/2021	Fiscalpower:	
Expertise Mileage:	146754	Power Kw:	190
Bodytype:		Body colour	Shadow Black
Gearbox:	Automatic	Paint type	Opaque
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	352
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Lining leather
GPS		Panoramic roof
Autom climate control		Rear parking sensors
Radio multimedia		Rear view camera

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 60 / 18 / 104 / Y / Aluminium	5,3 mm	Continental	Summer
	Right	225 / 60 / 18 / 104 / Y / Aluminium	5,4 mm	Continental	Summer
Rear	Left	225 / 60 / 18 / 104 / Y / Aluminium	4,9 mm	Continental	Summer
	Right	225 / 60 / 18 / 104 / Y / Aluminium	5,0 mm	Continental	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Dashboard, Scratch(es), Smart repair



Shutter / cover, Scratch(es), Replace



Wing FL, Dent(s), Repair and paint (complete)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Polish



Wing RL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Bad repair, Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Bumper RM, Scratch(es), Replace



Seat cover FL, Worn, Replace



Side window trim FL, Broken, Replace



Kenteken	L950JX
Merk Model	Ford Mustang Mach-E 198kW/ 75,7kWh RWD automaat
Brandstofsoort	Elektrisch
Datum deel1	06-07-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
23-06-25	115.780	APK
23-06-25	115.780	Onderhoudsbeurt
23-06-25	115.780	Remvloeistof
30-05-23	49.038	Onderhoudsbeurt