



Skoda Sc

Vinnumber:	TMBEP6NWXN3082245	Versionname:	
First Registrationdate:	17/05/2022	Fiscalpower:	
Expertise Mileage:	103687	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	MAN 5 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1124
Fueltype:	Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	1	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

205/50/17/93 H				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/50 R 17 93 H
Tyre size FR				205/50 R 17 93 H
Tyre size RL				205/50 R 17 93 H
Tyre size RR				205/50 R 17 93 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2063,30
Ignition key, Missing, Replace	350,09



Bumper F, Scratch(es), Repair and paint (complete)	296,58
--	--------



Bumper moulding F, Scratch(es), Acceptable	0,00
--	------



Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------



Door FL, Dent(s) and scratch(es), Repair and paint (complete)	445,79
---	--------



Door RL, Scratch(es), Acceptable	0,00
----------------------------------	------



Bumper R, Scratch(es), Repair and paint (complete)	296,58
--	--------



Door FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Door RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Roof, Chemical polution, Repair and paint (complete)	674,26
--	--------

