



Renault Captur: N835HV

Vinnumber:	VF1RJB00168056344	Versionname:	Captur 1.3 103kW GPF Intens EDC
First Registrationdate:	25/10/2021	Fiscalpower:	
Expertise Mileage:	121028	Power Kw:	103
Bodytype:		Body colour	Two-tone Bleu Celadon / Gris Highland
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Hybrid Petrol	Parking lot	1166
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Lining semi-leather
Autom climate control		Rear parking sensors
Radio multimedia		Tow bar removable
		Rear view camera

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 60 / 17 / 100 / H / Aluminium	5,4 mm	Michelin	Winter
	Right	215 / 60 / 17 / 100 / H / Aluminium	6,3 mm	Michelin	Winter
Rear	Left	215 / 60 / 17 / 100 / H / Aluminium	5,9 mm	Michelin	Winter
	Right	215 / 60 / 17 / 100 / H / Aluminium	6,3 mm	Michelin	Winter

Assistance equipment

Number of charging cables (rapid charge)	0
--	----------


Interior, Stain, Cleaning




Door trim FR, Scratch(es), Replace



Bumper corner RR, Scratch(es), Repair and paint (complete)



Roof, Chemical polution, Polish



Kenteken	N835HV
Merk Model	Renault Captur 1.3 103kW GPF Intens EDC
Brandstofsoort	Benzine
Datum deel1	25-10-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
15-10-25	107.304	Accu
15-10-25	107.304	APK
15-10-25	107.304	Bougie
15-10-25	107.304	Luchtfilter
15-10-25	107.304	Onderhoudsbeurt
15-10-25	107.304	Remschijf + blokken voor
15-10-25	107.304	Ruitenwisserblad(en) voorzijde
15-10-25	107.304	Sleutelbatterij
14-11-24	80.668	Onderhoudsbeurt
14-11-24	80.668	Remvloeistof
04-12-23	56.700	Bougie
04-12-23	56.700	Luchtfilter
04-12-23	56.700	Onderhoudsbeurt
04-12-23	56.700	Sleutelbatterij
22-08-23	47.534	Airo vulling
26-10-22	26.519	Onderhoudsbeurt