



CITROËN C3 Origin: 9563-MRT

Vinnumber:	VF75XYHTURT080978	Versionname:	Citroen BlueHdi 75KW (100CV) Plus berlina con portón 75kW 5P manual
First Registrationdate:	30/05/2024	Fiscalpower:	
Expertise Mileage:	91137	Power Kw:	
Bodytype:	Berline	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Certificate of Conformity:	No		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options


Number of keys total:	2	Luggage cover:	
Number keys remote:	1		
Windows electric F:			
Cruise Control:			
Steering wheel multifunctional:			
Radio multimedia:			
Type of climate control:	Autom climate control		

Tyres

205/55/16/94 V				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL:				4.0
Tyre profile depth FR:				4.0
Tyre profile depth RL:				5.0
Tyre profile depth RR:				5.0
Tyre size FL:				205/55 R 16 94 V
Tyre size FR:				205/55 R 16 94 V
Tyre size RL:				205/55 R 16 94 V
Tyre size RR:				205/55 R 16 94 V
Tyre type FL:				Summer
Tyre type FR:				Summer
Tyre type RL:				Summer
Tyre type RR:				Summer
Tyre make FL:				259
Tyre make FR:				259
Tyre make RL:				261
Tyre make RR:				261

Assistance equipment

Repair kit:	Yes
MOT certificate, Missing, Repair/replace (lump sum)	



Registration document, Missing, Repair/replace (lump sum)



Fender moulding RL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Mirror side repeater L, Broken, Replace



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Paint



Wheel cover FR, Scratch(es), Replace



Mirror side repeater R, Broken, Replace



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Paintless dent repair



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check

