

INSPECTION REPORT

End of contract

GENERAL INFO

File	315596
License plate	2BWZ860
Vehicle identification number	YV1UZZK5VDN1073678
Dossier	2021 285 070
Make	Volvo XC60 B4 D Momentum Pro G
Mileage	200585
First registration	25/04/2022
client availability date	17/06/2026
inspectionDate	26/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
18	Bumper Front / Spoiler / Replace	N
194	Door Rear Right // Repair & Painting	N
214	Door Front Right // Repair & Painting	N
35	Front Bonnet // Polish	Y
66	Wing Front Left // Polish	Y
80	Door Front Left // Smart Repair Small	N
87	Door Front Left / Trim / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	Y
116	Wing Rear Left // Polish	Y
124	Light / Rear left / Replace	Y
134	Bumper Rear // Repair & Painting	N
147	Back Side / Whiper Arm / Replace	N
153	Rear Bonnet // Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
183	Wing Rear Right // Painting	N
201	Rocker Panel Right // Smart Repair Medium	Y
222	Side View Mirror Right // Painting	Y
228	Side View Mirror Right / Direction Indicator / Replace	N
236	Wing Front right // Polish	Y
311	Wheel Alloy Front Left // Repair	Y
341	Wheel Alloy Front Right // Repair	Y
346	Tyre Front Right // Replace	N
533	Trunk Compartment / Side Cover Right / Replace	N
534	Trunk Compartment / Carpet / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures



Back Side / Whiper Arm / Replace-cracked




Tyre Front Right // Replace-tear



Interior Cleaning // Small-stain



Light / Rear left / Replace-scratch



Wing Rear Left // Polish-scratch



Door Rear Left // Painting-scratch



Door Front Left / Trim / Replace-scratch




Door Front Left // Smart Repair Small-scratch



Wheel Alloy Front Left // Repair-scratch



Wing Front Left // Polish-scratch



Front Bonnet // Polish-scratch



Wing Rear Right // Painting-scratch



Rear Bonnet // Painting-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wheel Alloy Front Right // Repair-scratch



Wing Front right // Polish-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch



Side View Mirror Right // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Trunk Compartment / Carpet / Replace-scratch




Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rocker Panel Right // Smart Repair Medium-scratch





Bumper Rear // Repair & Painting-scratch + dent






Bumper Front / Spoiler / Replace-scratch + dent



Bumper Front // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent