APPRAISAL REPORT



VEHICLE IDENTIFICATION

Driver name:	HM Tongeren
Make:	VOLVO
Model / version:	XC60
Wine:	YV1UZK5VDM1855367
Plate:	2AKR417
Mileage:	111329
SOH:	
First registration:	27/04/2021
Color:	PINE GREY ME

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	✓
Type of lining:	Leather
Board computer reset:	✓

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book	
Number of keys:	2
Original key:	✓


PICTURES













































WINE INFORMATION

Radio	Navigation system	12 speakers
Phone	Automatic transmission	8 reports
Front-wheel drive	LED spotlights	Fog lights
Headlight washers	Chrome window surround	Material: alloy
Reference letter (J)	Front diameter 19	Rear diameter 19
Front width 7.5	Rear width 7.5	Front diameter 19
Rear diameter 19	Front height 55	Rear height 55
Forward speed index V	Rear speed index V	Front width 235
Rear width 235	Stationary heating	Front center armrest
Leather interior finish	Diesel Hybrid	1969 cm3
2.00 liters	145 kW	197 hp
Varnished mica	Parts delivered painted	Front disc brakes

Mirrors delivered painted

Front left seat with memory settings
Front parking assistance
360° camera
Electrically operated trunk opening
Fixotoit
Autonomous emergency braking assistance (urban)
extended driver's seat
Keyless Entry

active grille shutter system
"Inscription Type" grille
AdBlue system
combined instruments with 12.3" monitor
Engine Type "VEA" Generation 3
lower door trim painted with chrome insert

Automatic day/night interior rearview mirror
Rear headrest
Rear parking assistance
Automatic distance control
rain sensor windshield wiper
Passenger airbag can be deactivated
Blind spot warning system

VIN -M-722 759
electric mirrors

interior lighting package
electric tank gate
12V 80Ah battery
long fuel pump
running boards with "Volvo" logo

Electrically adjustable front left seat

Heated steering wheel
Parking assistance
Heads-up display
Electric retractable towbar
Knee airbag
Forward collision warning

Air Quality "IAQS"
DVD player with 2 screens integrated into the front headrests
illuminated door handle
low pressure braking system
dual exhaust (accessory)
additional 5 48V battery
Torslanda (Sweden)

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
GPS:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Heated front seats:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlight type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Kind	Rims	Runflat
Front left	3 mm			Summer	Aluminum	?
Front right	3 mm			Summer	Aluminum	?
Rear left	3 mm			Summer	Aluminum	?
Rear right	3 mm			Summer	Aluminum	?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Rental	Damage type
1	Dashboard - Boordcomputer resetten	Not original part

Total: 1



ACCEPTABLE / NOT TO BE INVOICED

#	Rental	Damage type	Renta®	Repaired	Already invoiced
2	Bodywork	Teeth and scratches	✓	✗	✗

Total: 1

DAMAGE DETAILS

1 - Dashboard - Boordcomputer resetten - Not original part


2 - Bodywork - Dent(s) and scratch(es) - Renta®



































SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

17/09/2026 15:14

