

## 2-FAW-654

2-FAW-654 · TS 1.8 Hybrid Dynamic + Business pack · 6 August 2026 ·  
Zaventem (BE)

### Specifications

|                      |                                       |                   |                                     |
|----------------------|---------------------------------------|-------------------|-------------------------------------|
| License Plate Number | 2-FAW-654                             | Fuel Type         | Hybrid Gasoline                     |
| Manufacturer         | TOYOTA                                | VIN               | SB1ZB3AE20E091518                   |
| Model                | Corolla                               | Cylinder Capacity | 1.798 <sup>cm3</sup>                |
| Model Versions       | TS 1.8 Hybrid Dynamic + Business pack | Transmission Type | Automatisch geschakelde Transmissie |
|                      |                                       | First Admission   | 11-03-2024                          |
| Body Type            | 5 door hatchback                      | Odometer          | 82.794 <sup>Km</sup>                |
| Color                | Silver                                | Numer Of Keys     | 2                                   |
| Paint Type           | Metallic                              | Interior          | Grey                                |
| Production Year      | 2024                                  | Number Headrests  | 5                                   |
| KW                   | 72                                    |                   |                                     |

## Images





## Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

## Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance 02-02-2026

Last maintenance odometer 65.524

Previous Repairs Unknown

## Tire Specifications

| Tire            | Profile         | Brand    | Width             | Aspect Ratio     | Radial             | Type       |
|-----------------|-----------------|----------|-------------------|------------------|--------------------|------------|
| Front Left      | 4 <sup>mm</sup> | Semperit | 205 <sup>mm</sup> | 55 <sup>mm</sup> | 16 <sup>inch</sup> | All Season |
| Rear Left       | 4 <sup>mm</sup> | Semperit | 205 <sup>mm</sup> | 55 <sup>mm</sup> | 16 <sup>inch</sup> | All Season |
| Front Right     | 4 <sup>mm</sup> | Semperit | 205 <sup>mm</sup> | 55 <sup>mm</sup> | 16 <sup>inch</sup> | All Season |
| Rear Right      | 4 <sup>mm</sup> | Semperit | 205 <sup>mm</sup> | 55 <sup>mm</sup> | 16 <sup>inch</sup> | All Season |
| Spare Tire Type | Compressor      |          |                   |                  |                    |            |

## Damages



Damage Part

Damage Type

Notes

Repair Type

Acceptable

Frontdoor – Left

Damaged

Sierlijst

Acceptable

Yes



Damage Part

Damage Type

Repair Type


Acceptable

Fender – Rear Right

Small scratch(es)

Polish

No



Damage Part

Damage Type

Repair Type

Acceptable

Skirt – Right

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Alloy – Right Front

Damaged

Rim repair

No



|                |                       |                      |            |
|----------------|-----------------------|----------------------|------------|
| Damage Part    | Damage Type           | Repair Type          | Acceptable |
| Bumper – Front | Dent(s) & Scratch(es) | Panelbeating & Spray | No         |



|                    |             |             |            |
|--------------------|-------------|-------------|------------|
| Damage Part        | Damage Type | Repair Type | Acceptable |
| Alloy – Left Front | Damaged     | Rim repair  | No         |



|             |               |             |            |
|-------------|---------------|-------------|------------|
| Damage Part | Damage Type   | Repair Type | Acceptable |
| Roof        | Small dent(s) | Restyle     | No         |



|                  |               |             |            |
|------------------|---------------|-------------|------------|
| Damage Part      | Damage Type   | Repair Type | Acceptable |
| Frontdoor – Left | Small dent(s) | Acceptable  | Yes        |



Damage Part

spoiler RB

Damage Type

small dents / small scratches

Repair Type

Panelbeating & Spotrepair

Acceptable

No



Damage Part

Bumper – Rear

Damage Type

small dents / small scratches

Repair Type

Panelbeating & Spray

Acceptable

No



Damage Part

Windscreen – Rear

Damage Type

Broken

Notes

Ruitenwischerblad

Repair Type

Replace

Acceptable

No



Damage Part

Tailgate

Damage Type

Scratch(es)

Repair Type

Spray

Acceptable

No