



OPEL MOVANO:

Vinnumber:	W0VMRW602KB176594	Versionname:	2.3 CDTi 81kW L3H2 3.5T
First Registrationdate:	12/04/2019	Fiscalpower:	
Expertise Mileage:	157452	Power Kw:	81
Bodytype:		Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:		Parking lot:	Icv22
Fueltype:	Diesel		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	1	Rear parking sensors:	
Cruise Control:		Type of Tow bar:	No Tow bar
Steering wheel multifunctional:			
Radio multimedia:			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	No GPS		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Tyres

225/65/16/110 R				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/65 R 16 110 R
Tyre size FR				225/65 R 16 110 R
Tyre size RL				225/65 R 16 110 R
Tyre size RR				225/65 R 16 110 R
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	1209,54
Ignition key, Missing, Replace:	262,56



Steering wheel, Worn, Acceptable

0,00



Seat cover FL, Damaged, Replace

413,11



Interior, Dirty, Cleaning

175,04



Bumper F, Scratch(es), Acceptable

0,00



Outside rear-view mirror housing L, Scratch(es), Acceptable

0,00



Wing RL, Dent(s) and scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)

326,10



Wing RR, Dent(s) and scratch(es), Acceptable

0,00



Wheel cover RR, Missing, Replace

32,73



Bodywork, Not original part, Remove lettering

0,00

