MACADAM







Peugeot 308 (UKL): 2CSF346

Vinnumber:	**VR3FPHNPLNY611040**	Versionname:	**308 Active Pack 1.2 PureTech S&S 110pk/cv 5p**
First Registrationdate:	**8/11/2022**	Fiscalpower:	
Expertise Mileage:	**64580**	Power Kw:	**81**
Bodytype:		Type of rims (mounted)	**Steel**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**9700.0**		
Maintenance	**5 maand**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**205/55/16/91 V**			
	Fr.L.	**Goodyear: 4 mm**	Fr.R.	**Goodyear: 4 mm**
	Re.L.	**Goodyear: 4 mm**	Re.R.	**Goodyear: 4 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**205/55 R 16 91 V**
Tyre size FR	**205/55 R 16 91 V**
Tyre size RL	**205/55 R 16 91 V**
Tyre size RR	**205/55 R 16 91 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Floor covering FL, Worn, Check




Seat cover FL, Stain, Acceptable




Seat cover FR, Stain, Acceptable




Bonnet, Scratch(es), Acceptable







Bumper F, Scratch(es), Spot repair





Door FL, Scratch(es), Acceptable





Outer door handle FL, Scratch(es), Acceptable




Step L, Dent(s), Acceptable




Door RL, Dent(s) and scratch(es), Acceptable





Wheel cover FL, Scratch(es), Replace










Wheel cover RL, Scratch(es), Replace






Rear bulkhead lining, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable










Step R, Scratch(es), Acceptable





Wheel cover RR, Scratch(es), Acceptable





Wing RR, Scratch(es), Acceptable





Door RR, Dent(s) and scratch(es), Acceptable







Door FR, Scratch(es), Acceptable






Outer door handle FR, Scratch(es), Acceptable




Roof pillar R, Scratch(es), Acceptable




Roof, Scratch(es), Acceptable




Onderhoudshistorie van: VR3FPHNPLNY611040

ALPHABET

Kenteken	2CSF346
Merk Model	Peugeot 308 Active Pack 1.2 PureTech S&S 110pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	11/8/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
3/11/26	54,523	50000 km	Uitvoeren
3/11/26	54,523	bougie	Vervangen
3/11/26	54,523	klein materiaal	N.v.t.
3/11/26	54,523	luchtfilter	Vervangen
3/11/26	54,523	luchtfilter interieur	Vervangen
3/11/26	54,523	ruitenwisserrubber achter	Vervangen
3/11/26	54,523	ruitenwisserrubber vooraan	Vervangen
2/12/25	33,122	klein materiaal	N.v.t.
2/12/25	33,122	luchtfilter interieur	Vervangen
2/12/25	33,122	onderhoud 2e jaar	Uitvoeren
2/12/25	33,122	remvloeistof	Vervangen
12/13/23	14,291	klein materiaal	N.v.t.
12/13/23	14,291	luchtfilter interieur	Vervangen
12/13/23	14,291	onderhoud 12 maand	Uitvoeren