Technician
Marcel Peeters

2-EXV-852

2-EXV-852 · ST Line X 1.0i EcoBoost 155pk - ST Line X 1.0i EcoBoost 155pk - 114kW - Mhev A7 -Clipper114kW - Mhev A7 -Clipper · 4 November 2026 · Zaventem Brussel

Specifications

License Plate Number	2-EXV-852
Manufacturer	FORD
Model	Focus Wagon
Model Versions	ST Line X 1.0i EcoBoost 155pk - ST Line X 1.0i EcoBoost 155pk - 114kW - Mhev A7 - Clipper114kW - Mhev A7 -Clipper
Body Type	Station Wagon
Color	Grey
Paint Type	Metallic
Production Year	2024
KW	114
Fuel Type	Gasoline

VIN	WF0PXXGCHPRB65550
Cylinder Capacity	999 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	01-03-2024
First Registration	01-03-2024
Odometer	69.647 Km
Numer Of Keys	2
Interior	Black – Cloth
Number Headrests	5

Images
































Accessories

ABS	Electrically adjustable exterior mirrors
Airbags	Front & rear parking sensors
Alloy wheels	Leather steering wheel
Audio System	Navigation system
Automatic air conditioning	Rear view camera
Bluetooth car kit	Roller cover / parcel shelf
Central door locking	Seat heating
Centre armrest	Steering wheel multifunction
Cruise control	Steeringwheel – Heated
Electric rear windows	Windscreen – Heated
Electric windows front	

Condition

Condition exterior	Adequate	Maintenance Remarks	Batterij sleutel vervangen
Condition interior	Adequate	Previous Repairs	Unknown
Last Maintenance Unknown			

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	3 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Rear Left	4 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Front Right	3 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Rear Right	4 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Spare Tire Type	Compressor					

Damages





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Small dent(s)	Restyle	No





Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Small scratch(es)	Touch-up / Polish	No





Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes







Damage Part	Damage Type	Repair Type	Acceptable
Grille	Broken	Replace	No







Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Front	Damaged	Acceptable	Yes





Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	Dent(s)	Panelbeating & Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No