



Make: BMW
Model / version: IX
Vin: WBY11CF090CK45886
Plate:
Mileage: 142256
SOH: 99 %
First registration: 09/05/2022
Color: Sapphire Bla


ADDITIONAL INFORMATION




Category:
Transmission:
Interior color:
Metallic paint: ✓
Type of lining: Leather
Board computer reset: ✗

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✓
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✓

PICTURES





VIN INFORMATION

depuis 03.22

climatisation automatique à 4 zones
tuner DAB
filet de séparation coffre
vitrage ar avec protection solaire

pack Sport avec caractéristiques
spécifiques supplémentaires
système d'accès confort
chargeur sans fil
Design intérieur Suite
protection acoustique des piétons

liquide de climatisation R1234YF

BMW Iconic Sounds Electric
garnissage pavillon anthracite
sièges av chauffants
système d'appel d'urgence légal

attache-remorque pivotant
protection des piétons active
éléments intérieurs Clear&Bold

caméra habitacle
255/50 R 21 .. Y
pavillon panoramique en verre "Sky
Lounge"
spécifique Europe

électrique 240 kW
9 J x 21 Alu noir ii unie
indicateur de pression des pneus
2 couches métallisée

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	✓	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✓
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	4 mm			Summer	Aluminium	?
Front right	4 mm			Summer	Aluminium	?
Rear left	4 mm			Summer	Aluminium	?
Rear right	4 mm			Summer	Aluminium	?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
3	Door FL	Scratch(es)
4	Windscreen	Crack

Total: 2

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
1	Interior	Damaged	✓	✗	✗
2	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 2

DAMAGES DETAILS

3 - Door FL - Scratch(es)



4 - Windscreen - Crack



1 - Interior - Damaged - Renta®



2 - Bodywork - Dent(s) and scratch(es) - Renta®





SIGNATURE

Expert

03/08/2026 10:53

