


Titanium 1.0i Ecoboost 100pk 74kw · 16 April 2026 · Zaventem  
(BE)

### Specifications

License Plate Number	2-ESY-933	Fuel Type	Gasoline
Manufacturer	FORD	VIN	WF0JXXGAHJPD33830
Model	Fiesta	Cylinder Capacity	998 <sup>cm<sup>3</sup></sup>
Model Versions	Titanium 1.0i Ecoboost 100pk 74kw	Transmission Type	Handmatig geschakelde transmissie
Body Type	5 door hatchback	First Admission	18-01-2024
Color	Grey	Odometer	75.312 <sup>Km</sup>
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Black
KW	74	Number Headrests	5

# Images





## Accessories

ABS

Airbags

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Leather steering wheel

Rear parking sensors

Roller cover / parcel shelf

Steering wheel multifunction

## Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

## Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 <sup>mm</sup>	Delinte	195 <sup>mm</sup>	60 <sup>mm</sup>	15 <sup>inch</sup>	All Season
Rear Left	4 <sup>mm</sup>	Continental	195 <sup>mm</sup>	60 <sup>mm</sup>	15 <sup>inch</sup>	All Season
Front Right	4 <sup>mm</sup>	Delinte	195 <sup>mm</sup>	60 <sup>mm</sup>	15 <sup>inch</sup>	All Season
Rear Right	4 <sup>mm</sup>	Continental	195 <sup>mm</sup>	60 <sup>mm</sup>	15 <sup>inch</sup>	All Season
Spare Tire Type		None				

## Damages



Damage Part

Damage Type

Repair Type

Acceptable

Wheelcover - Left Rear

Damaged

Replace

No



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Rear Left

Dent(s)

Panelbeating & Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Reardoor - Left

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Wheelcover - Left Front

Damaged

Replace

No



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Front Left

Small dent(s)

Panelbeating & Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Hood

Fainted Paint

Polish

No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Front	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Right Front	Damaged	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Front Right	Dent(s)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Right	Scratch(es)	Spray	No



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Rear Right

small dents / small scratches

Panelbeating & Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Bumper - Rear

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Tailgate

Small scratch(es)

Polish

No