



Ford Mustang: L239JP

Vinnumber:	WF0TK1EM9MMA17161	Versionname:	Mustang Mach-E 190kW/ 75,7kWh RWD automaat (NEDC)
First Registrationdate:	4/06/2021	Fiscalpower:	
Expertise Mileage:	90824	Power Kw:	190
Bodytype:		Body colour	Premium Metaallak: Star White
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	787
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	Yes		

Options

Number of keys total	2	Lining leather
GPS		Panoramic roof
Autom climate control		Rear parking sensors
Radio multimedia		Rear view camera

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 60 / 18 / 104 / V / Aluminium	4,4 mm	Continental	Summer
	Right	225 / 60 / 18 / 104 / V / Aluminium	3,3 mm	Continental	Summer
Rear	Left	225 / 60 / 18 / 104 / V / Aluminium	3,7 mm	Continental	Summer
	Right	225 / 60 / 18 / 104 / V / Aluminium	3,7 mm	Continental	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Service, Maintenance, Execute



Seat cover FL, Worn, Replace



Wing RL, Bad repair, Repair and paint (complete)



Door FL, Dent(s), Repair and paint (complete)



Door RL, Chemical polution, Polish



Bumper F, Scratch(es), Polish



Door FR, Dent(s), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Kenteken	L239JP
Merk Model	Ford Mustang Mach-E 198kW/ 75,7kWh RWD automaat
Brandstofsoort	Elektrisch
Datum deel1	04-06-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
15-05-25	73.629	APK
15-05-25	73.629	Onderhoudsbeurt
15-05-25	73.629	Remvloeistof
15-05-25	73.629	Ruitenwischerblad(en) achterzijde
15-05-25	73.629	Ruitenwischerblad(en) voorzijde
15-05-25	73.629	Sleutelbatterij
15-05-25	73.629	Vervanging band
27-11-23	43.671	Reparatie band(en)
12-06-23	35.228	Onderhoudsbeurt