



Volkswagen Arteon

| | | | |
|-------------------------------------|--------------------------|-------------------------|------------------|
| Vinnnumber: | VWVZZZ3HZNE504057 | Versionname: | |
| First Registrationdate: | 6/01/2022 | Fiscalpower: | |
| Expertise Mileage: | 175200 | Power Kw: | 115 |
| Bodytype: | | Body colour: | Black |
| Gearbox: | Automatic | Type of rims (mounted): | Aluminium |
| Transmission: | | Parking lot: | 1706 |
| Fueltype: | Hybrid Petrol | | |
| Maintenance: | OK | | |
| Type of rims (mounted): | Aluminium | | |
| Certificate of Conformity: | Yes | | |
| Category: | Passenger Car | | |
| Registration Certificate Car (BE): | Yes | | |
| Registration Certificate Home (BE): | No | | |

Options

| | | | |
|---------------------------------|------------------------------|------------------------|-------------------|
| Number of keys total: | 2 | Seats electric F L: | |
| Cruise Control: | | Seats electric F R: | |
| Steering wheel multifunctional: | | Panoramic roof: | |
| Seats F heated: | | Luggage cover: | |
| Radio multimedia: | | Front parking sensors: | |
| Type of headlighting: | Headlighting LED | Rear parking sensors: | |
| Type of GPS: | GPS big screen color | Type of Tow bar: | No Tow bar |
| Type of Lining: | Lining leather | | |
| Type of climate control: | Autom climate control | | |
| Type of GPS storage: | HD | | |

Limited Technical Inspection

Tyres

| 245/45/18/100 V | | | | |
|-----------------------|-------|------------------------|-------|--------------------------|
| Winter tyres: | Fr.L. | Firestone: 2 mm | Fr.R. | Firestone: 2 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |
| Tyre profile depth FL | | | | 2.0 |
| Tyre profile depth FR | | | | 2.0 |
| Tyre profile depth RL | | | | 5.0 |
| Tyre profile depth RR | | | | 5.0 |
| Tyre size FL | | | | 245/45 R 18 100 V |
| Tyre size FR | | | | 245/45 R 18 100 V |
| Tyre size RL | | | | 245/45 R 18 100 V |
| Tyre size RR | | | | 245/45 R 18 100 V |
| Tyre type FL | | | | Winter |
| Tyre type FR | | | | Winter |
| Tyre type RL | | | | Winter |
| Tyre type RR | | | | Winter |
| Tyre make FL | | | | 258 |
| Tyre make FR | | | | 258 |
| Tyre make RL | | | | 261 |
| Tyre make RR | | | | 261 |

Assistance equipment

| | | | |
|---|----------|-------|------------|
| Number of charging cables (normal): | 1 | Jack: | Yes |
| Number of charging cables (rapid charge): | 1 | | |

| | |
|----------------------------------|----------------|
| Total cost ex VAT: | 1708,83 |
| Seat cover FL, Damaged, Replace: | 1105,78 |



Backrest cover FL, Worn, Acceptable 0,00



Seat cover FR, Worn, Acceptable 0,00



Windscreen, Stone chip(s), Windscreen repair 0,00



Bumper F, Scratch(es), Repair and paint (complete) 296,58



Bumper spoiler F, Dent(s) and scratch(es), Replace 173,44



Alloy rim FL, Scratch(es), Acceptable 0,00



Outside rear-view mirror housing L, Scratch(es), Acceptable 0,00



Door FL, Dent(s) and scratch(es), Acceptable 0,00



Door RL, Repaired, Acceptable 0,00



Wing RL, Repaired, Acceptable 0,00



Boot lid covering R, Scratch(es), Acceptable 0,00



Bumper R, Repaired, Acceptable 0,00



Wheel aperture RR, Scratch(es), Acceptable 0,00



Wing RR, Dent(s) and scratch(es), Acceptable 0,00



Door RR, Dent(s) and scratch(es), Acceptable 0,00



Step R, Dent(s), Acceptable 0,00



Outside rear-view mirror housing R, Scratch(es), Acceptable 0,00



Alloy rim FR, Scratch(es), Repair and paint (complete)

133,03



Roof, Scratch(es), Acceptable

0,00

