

MACDAM

Kia Niro FL'19 BEV

Vehicle information




Make:	Kia	License:	
Gearbox:	Automatic	Body color:	
Model:	Niro FL'19 BEV	VIN:	KNACC81GFL5051887
Fuel type:	Electric	Power:	150 kW
Version:	Niro EV 64kWh 11 f.3 Dynamic	First registration	29/09/2020
Mileage:	158116 km	N° of doors:	

Damage summary

Front	2
Left	4
Rear	3
Right	2

Commercial pictures





Batterijcertificaat

Datum van diagnose: 08/07/2026

Raadpleeg het Moba-certificaat door deze QR-code te scannen

100%

Status van de gezondheid (SOH)*

Kia e-Niro

VIN : KNACC81GFL5051887
Kilometerstand : 158.116 km

*SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie

Meer weten over www.get-moba.com

CARA
Caravan & Caravan Accessory Health Check

Options according to the inspector					
Central consol F	Yes	GPS	Yes	Hook	Yes
Radio multimedia	Yes	Rear view camera	Yes	Telephone equipment	Yes

Damages

Alloy rim FL
Scratch(es)
Repair and paint (complete)
Left



Bonnet
Stone chip(s)
Repair and paint (complete)
Front



Bumper F
Scratch(es)
Repair and paint (partial)
Front




Bumper R
Scratch(es)
Repair and paint (complete)
Rear



Charging cable (normal)
Missing
Replace
Rear



Door FL
Scratch(es)
Repair and paint (complete)
Left



Door RL
Scratch(es)
Repair and paint (partial)
Left



Door RR
Scratch(es)
Repair and paint (complete)
Right




Tailgate / Boot
Scratch(es)
Repair and paint (complete)
Rear



Wing FR
Scratch(es)
Repair and paint (complete)
Right



Wing RL
Dent(s) and scratch(es)
Repair and paint (complete)
Left



Tyres	
	Front Left
	Summer
	215/55/17/98/W
	Bridgestone
	3.7 mm
	Front Right
	Summer
	215/55/17/98/W
	Bridgestone
	3.7 mm
	Rear Left
	Summer
	215/55/17/98/W
	Bridgestone
	5.7 mm
	Rear Right
	Summer
	215/55/17/98/W
	Bridgestone
	5.3 mm

Checks			
CO2 Emission	0	Digital maintenance	N/A
GPS storage	Yes	Luggage cover	Yes
Number head rests	5	Number of charging cables (rapid charge)	1
Number of keys total	2	Reset to factory settings	Yes, vehicle is reset to factory settings
Service book	N/A	User's manual	Yes

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.