



PEUGEOT 308 SW: FS-352-RC

Vinnumber:	VF3LCYHZRLS191544	Versionname:	PEUGEOT 308 SW BlueHdi 130 EAT8 S&S Allure Business VP [5P] bva 8-130CH-7cv (break)
First Registrationdate:	14/09/2020	Fiscalpower:	
Expertise Mileage:	999999	Power Kw:	96
Bodytype:	Break	Body colour:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	No	Dashboard color:	Black
Battery functioning:	No		
Vehicle running:	No		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Tow bar	
Number keys remote	2	Radio	
GPS big screen color		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Headlights Xenon/LED/Laser	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	
Steering wheel leather			Lining Other
Type of climate control	Autom climate control		Lining Leather

Tyres

	205/55/16/91 H			
Summer tyres:	Fr.L.	Michelin: 55%	Fr.R.	Michelin: 60%
	Re.L.	Michelin: 55%	Re.R.	Michelin: 65%
Tyre profile depth FL				4.5
Tyre profile depth FR				4.4
Tyre profile depth RL				4.5
Tyre profile depth RR				4.1
Tyre size FL				205/55 R 16 91 H
Tyre size FR				205/55 R 16 91 H
Tyre size RL				205/55 R 16 91 H
Tyre size RR				205/55 R 16 91 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Backrest cover RR, Dirty, Cleaning			



Seat cover FL, Dirty, Cleaning



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre RR, Out of tolerance, Replace



Door RL, Dent(s), Repair and paint (complete)



Bumper moulding FL, Scratch(es), Replace



Bumper F, Scratch(es), Paint



Wing RR, Dent(s), Repair and paint (complete)



Tailgate / Boot, Not functioning (well), Check



Bumper R, Deformed / Strained, Repair and paint (complete)



Historique Maintenance

Immatriculation: FS-352-RC Date de 1ère immatriculation: 14/09/2020

Modèle: Peugeot 308 SW BlueHDi 130 EAT8 S&S Allure Business VP [5P] bva 8-130CH-7cv (break)

Date	Kilométrage	Fournisseur	Descriptif
21/01/2025	169.260	PAILHON ET FILS	RECYCLAGE
	0		LIQUIDE DE REFROIDISSEMENT RPLT
	0		DIVERS CLIM
	0		REVISION
25/04/2025	148.225	PAILHON ET FILS	RECYCLAGE
	0		ADBLUE
	0		DIVERS REFROIDISSEMENT
	0		DISQUES PLAQUETTES AV RPLT
	0		REVISION
22/12/2023	125.633	PAILHON ET FILS	REVISION
	0		RECYCLAGE
	0		ADBLUE
	0		COURROIE ACCESSOIRES RPLT
	0		DIVERS CLIM
	0		FILTRE A AIR RPLT
	0		REVISION
	0		FILTRE CLIM RPLT
05/07/2023	106.089	PAILHON ET FILS	BALAI ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		REVISION
	0		LIQUIDE DE FREIN
	0		ADBLUE
	0		RECYCLAGE
07/04/2023	97.491	PAILHON ET FILS	PLAQUETTES AV RPLT
	0		RECYCLAGE
12/12/2022	85.257	PAILHON ET FILS	RECYCLAGE
	0		DISQUES PLAQUETTES AR RPLT
05/05/2022	63.580	PAILHON ET FILS	REVISION ET CLIM
	0		REVISION ET CLIM
	0		REVISION ET CLIM
	0		RECYCLAGE
	0		ADBLUE

Historique Maintenance

Immatriculation: **FS-352-RC**

Date de 1ère immatriculation: **14/09/2020**

Modèle: **Peugeot 308 SW BlueHDi 130 EAT8 S&S Allure Business VP [5P] bva 8-130CH-7cv (break)**

Date	Kilométrage	Fournisseur	Descriptif
	0		REVISION ET CLIM
03/11/2021	42.515	PAILHON ET FILS	BALAI ESSUIE GLACE AR
	0		RECYCLAGE
	0		BALAIS ESSUIE GLACE AV
	0		REVISION
28/05/2021	22.012	PAILHON ET FILS	REVISION
	0		ADBLUE
22/03/2021	15.270	PAILHON ET FILS	ADBLUE