

## Expertise

Protocol number: 46265561  
Order No. / Reference: 26431371  
Inspection date: 25 Jun 2026

Manufacturer: Seat

Model: CUPRA Leon 2.0 TSI DSG

VIN: VSSZZZKLZNR055753



### Vehicle details

#### Manufacturer / Type / Model / Equipment

Seat CUPRA Leon 2.0 TSI DSG

**Vehicle Identification number** VSSZZZKLZNR055753

**Mileage (Read)** 102,674 km

**First registration** 23 May 2022

**Number of holders** 1

**Next periodical technical inspection** 05/2027  
(Report on hand)

**Power / Engine displacement** 180 kw / 1,984 ccm

**Fuel type / Cylinder** Petrol / 4

**Gearbox / Number of gears** Automatic / 7

**Type of drive** Front drive

**Type of vehicle** Saloon car

**Colour / colour code** Urban Silber Metallic

**Doors / Seats** 5 / 5

**Upholstery type** Cloth

**Colour of upholstery** Black-Anthracite



## Vehicle details

<b>Maintenance booklet / proof</b>	digital proof / complete	<b>Next maintenance in</b>	18,700 km
<b>Last service on / at</b>	02/2026 at 91,344 km		
<b>Key is / should be</b>	2 / 2	<b>FZG documents</b>	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		<b>Letter No.</b>	GJ872852
<b>Previous damage / Accident</b>	None detectable	<b>Repainting</b>	None detectable
<b>Inspection conditions</b>	sufficient	<b>Lifting equipment / pit</b>	No
<b>Test drive</b>	Not performed	<b>Engine function test</b>	Performed
<b>Manufacturer key number/ type code number</b>	7593 / AQR 00178		
<b>Emission standard</b>	EURO6;WLTP;AP;PI/CI; M, N1 I	<b>fine dust sticker</b>	
<b>Permitted total weight</b>	1,960 kg	<b>Empty weight</b>	

## Tyres

### Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/35 R19 91Y	Summer tyres on Light alloy	Hankook	6mm / 6mm
2)	235/35 R19 91Y	Summer tyres on Light alloy	Hankook	6mm / 6mm

### Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R18 92V	Winter tyres on Light alloy	Goodyear	7mm / 7mm
2)	225/40 R18 92V	Winter tyres on Light alloy	Pirelli	7mm / 7mm

### Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	125/70 R18 99M	Summer tyres on Steel	Sonstige	3 mm

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**



## Equipment

### Standard equipment

- Storage compartment in the doors
- Airbag: Passenger airbag deactivation
- Exterior mirror caps painted in "Dark Aluminium"
- CURA CONNECT
- Tachometer
- Electronic parking brake including auto-hold function
- Electric window regulator with anti-pinch protection and one-touch function
- Speed limiter
- Transmission: 7-speed DSG
- Heated rear window
- ISOFIX child seat restraint system, in the 2nd row left and right
- Headrests, 2 front
- Headrests, 3 rear
- Heated steering wheel
- front center armrest
- Fatigue detection
- Emergency call service
- Package: Light and Sight Package
- Radio: Digital radio reception DAB+
- Tire pressure monitoring system
- Wheels: Spare wheel as emergency wheel
- Servotronic
- Seat belts - three-point automatic, front and rear
- Seats: Driver's seat with height adjustment
- Seats: Rear seat backrest asymmetrically split and foldable
- Sun visor on driver and passenger side with make-up mirror and lighting
- Illuminated door sill trims, front
- Ultrasonic parking aid, rear
- Lashing eyes in the luggage compartment
- Virtual Cockpit
- thermal insulation glazing

### Extra equipment

- Airbag: Rear side airbag and driver's side knee airbag
- Paint finish: Metallic
- Package: Driving Assistance Package M for navigation system (Adaptive Cruise Control up to 210 km/h with predictive speed control PCC - High Beam Assist - Traffic Sign Recognition)

- Airbag: Airbag for driver and front passenger
- Electrically adjustable, folding and heated exterior mirrors
- third brake light
- Electronic differential lock (XDS) for front axle
- Drive Profile CUPRA
- Electronic Stability Control (ESC)
- luggage compartment cover
- Luggage compartment lighting
- Cruise control system (CCS)
- Illuminated glove compartment
- rear window wiper
- Keyless Go (engine start/stop button)
- Climatronic air conditioning with 3-zone temperature control
- Trim strips on the side windows (outside) in Glossy Black
- Steering wheel: CUPRA sport multifunction steering wheel with shift paddles
- Navigation system
- Otto particulate filter
- Package: Full LED package
- Radio accessories: 2 USB-C ports front / 2 rear (charging function)
- Side windows from the 2nd row of seats and rear window are dark tinted.
- Seats: Passenger seat with height adjustment
- Seats: Lumbar support for driver/passenger seat
- Seats: Front sports bucket seats in "Sharp Textil"
- Smart Ambient Light
- Lane departure warning system
- Start-stop system and recuperation
- Door trim in leather look
- Front Assist area monitoring system with City Emergency Braking function
- Electronic immobilizer
- Central locking with remote control

- Anti-theft alarm system including interior monitoring, backup horn and tow-away protection
- Radio accessories: Beats Audio™ sound system (10 speakers (with subwoofer), digital 12-channel amplifier, subwoofer, 340 watts total power)
- Wheels: Alloy wheels (4) 8J x 19" "Exclusive II Black/Silver", diamond-turned (tires 235/35 R 19)



## Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

## Value reducing factors

No.	Component group	Description
1	Front bumper	Front bumper - Scratched - Paint

## Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Mudguard - left side	Mudguard - left side - Stone chips - No deduction
4	Interior	Interior - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.
- Fahrzeugmodellbezeichnung laut Rechnung: "Seat CUPRA Leon 2.0 TSI DSG".
- Der beiliegende Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Additional tyres



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Damage 1: Front bumper: Front bumper - Scratched - Paint



Damage 1: Front bumper: Front bumper - Scratched - Paint



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VSSZZZKLZNR055753  
Hersteller / Modell: SEAT SEAT Leon 2.0 TSI DSG

Datum	KM-Stand	Beschreibung
19.02.2026	91.344	Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
22.05.2025	71.809	AU
31.01.2025	60.776	Bremsflüssigkeit; Bremsflüssigkeit ern; Getriebeöl ern/prüfen; Motoröl b. Wartung; Ölfilter ern; Ölwechsel - Hinterachse; Regelwartungsdienst; Reparatur Sonstiges; Wartung Sonstiges; Zündkerzen ern
04.11.2024	52.362	Systemtest/Eigendiagnose
05.12.2023	30.557	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges