



Polestar 2: L958TH

| | | | |
|-------------------------|--------------------------|-------------------------|---|
| Vinnumber: | LPSVSEDEEML026376 | Versionname: | Polestar 2 AWD 300kW/ 78kWh Pilot Plus |
| First Registrationdate: | 28/07/2021 | Fiscalpower: | |
| Expertise Mileage: | 70603 | Power Kw: | 300 |
| Bodytype: | | Body colour: | Void |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | | Type of rims (mounted): | Aluminium |
| Fueltype: | Electric | Parking lot: | 1656 |
| Number of seats: | 5 | | |
| Type of rims (mounted): | Aluminium | | |
| Maintenance needed: | No | | |

Options

| | | |
|-----------------------|----------|----------------------|
| Number of keys total | 2 | Panoramic roof |
| GPS | | Rear parking sensors |
| Autom climate control | | |
| Radio multimedia | | |

Tyres

| Location | Position | Measures | Depth | Make | Type |
|----------|----------|------------------------------------|--------|------------|--------|
| Front | Left | 245 / 40 / 20 / 99 / Y / Aluminium | 5,2 mm | Vredestein | Winter |
| | Right | 245 / 40 / 20 / 99 / Y / Aluminium | 5,0 mm | Vredestein | Winter |
| Rear | Left | 245 / 40 / 20 / 99 / Y / Aluminium | 5,2 mm | Vredestein | Winter |
| | Right | 245 / 40 / 20 / 99 / Y / Aluminium | 5,5 mm | Vredestein | Winter |

Assistance equipment

| | |
|--|----------|
| Number of charging cables (rapid charge) | 1 |
|--|----------|

Door FL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Polish



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper FM, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Wing RR, Stone chip(s), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace and paint



Tailgate / Boot, Scratch(es), Repair and paint (complete)



| | |
|-----------------------|--|
| Kenteken | L958TH |
| Merk Model | Polestar Polestar 2 AWD 300kW/ 78kWh Dual Motor Long Range |
| Brandstofsoort | Elektrisch |
| Datum deel1 | 28-07-21 |

| Datum reparatie | Kilometerstand | Reparatie omschrijving |
|-----------------|----------------|------------------------|
| 15-05-26 | 69.037 | Onderhoudsbeurt |
| 08-09-25 | 58.668 | APK |