

## 2-FWF-871

2-FWF-871 · Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT · 30 June 2026 · Zaventem (BE)

### Specifications

License Plate Number	2-FWF-871	Fuel Type	Hybrid Gasoline
Manufacturer	TOYOTA	VIN	JTNADADB20J020881
Model	Corolla	Cylinder Capacity	1.798 <sup>cm<sup>3</sup></sup>
Model Versions	Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	16-09-2024
Color	Black	Odometer	67.126 <sup>Km</sup>
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	103	Number Headrests	5

Images





## Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Rear view camera

Roller cover / parcel shelf

Steering wheel multifunction

## Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs

Unknown

## Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 <sup>mm</sup>	Uniroyal	215 <sup>mm</sup>	60 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Rear Left	6 <sup>mm</sup>	Uniroyal	215 <sup>mm</sup>	60 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Front Right	4 <sup>mm</sup>	Uniroyal	215 <sup>mm</sup>	60 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Rear Right	6 <sup>mm</sup>	Uniroyal	215 <sup>mm</sup>	60 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Spare Tire Type		None				

## Damages



Damage Part

Drivers seat

Damage Type

Stains & dirt

Repair Type

Cleaning

Acceptable

No



Damage Part

Reardoor - Left

Damage Type

Scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part

Frontdoor - Left

Damage Type

Small scratch(es)

Repair Type

Polish

Acceptable

No



Damage Part

Hood

Damage Type

Stonechipping

Repair Type

Acceptable

Acceptable

Yes



Damage Part

spoiler FB

Damage Type

Scratch(es)

Repair Type

Plastic Repair

Acceptable

No



Damage Part

Overfender

Damage Type

Scratch(es)

Repair Type

Replace

Acceptable

No



Damage Part

Damage Type

Repair Type

Acceptable

Bumper - Front

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor - Right

Damaged

Touch-up /  
Polish

No



Damage Part

Damage Type

Repair Type

Acceptable

Reardoor - Right

Damaged

Touch-up /  
Polish

No



Damage Part

Damage Type

Repair Type

Acceptable

Alloy - Right Rear

Damaged

Acceptable

Yes



Damage Part

Damage Type

Notes

Repair Type

Acceptable

Bumper - Rear

Scratch(es)

Middenstuk

Plastic Repair

No



Damage Part

Damage Type

Repair Type

Acceptable

Bumper - Rear

Small scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Tailgate

Small scratch(es)

Spray

No



Damage Part

Damage Type

Notes

Repair Type

Acceptable

Reardoor - Right

Scratch(es)

Bekleding

Cloth Repair

No



Damage Part

Damage Type

Repair Type

Acceptable

Skirt - Right

Scratch(es)

Spray

No