



VOLKSWAGEN CADDY MAXI VAN: EG-576-XV

Vinnumber:	WV1ZZZ2KZX044942	Versionname:	VOLKSWAGEN CADDY MAXI VAN 2.0 TDI MAXI 122 4MOTION VU [4P] bvm 6-122CH-7cv (fourgonnettesimple cabine)
First Registrationdate:	22/11/2016	Fiscalpower:	90
Expertise Mileage:	139461	Power Kw:	White
Bodytype:	Transporter	Body colour:	Opaque
Gearbox:	MAN 6 VIT	Paint type:	Dark Grey
Transmission:	4 Wheel-drive	Interior colour:	Steel
Fueltype:	Diesel	Type of rims (mounted):	Black
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	4		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	1	Radio	
Number keys remote	1	Seat cover lining	Lining Other
Windows electric F			
Cruise Control			
Type of climate control	Manual climate control		

Tyres

205/55/16/91 W				
Summer tyres:	Fr.L.	Michelin: 55%	Fr.R.	Michelin: 70%
	Re.L.	Michelin: 40%	Re.R.	Michelin: 40%
Tyre profile depth FL				4.5
Tyre profile depth FR				3.8
Tyre profile depth RL				5.6
Tyre profile depth RR				5.7
Tyre size FL				205/55 R 16 91 W
Tyre size FR				205/55 R 16 91 W
Tyre size RL				205/55 R 16 91 W
Tyre size RR				205/55 R 16 91 W
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	No	Jack	No
-------------	-----------	------	-----------

Seat cover FL, Burned, Replace



Roof liner, Stain, Cleaning



Remote ignition key, Missing, Repair/replace (lump sum)



Remote ignition key, Broken, Repair/replace (lump sum)



Tyre FR, Out of tolerance, Replace



Outer sill L, Dent(s), Replace and paint



Side wall RL, Dent(s), Repair and paint (complete)



Door FL, Dent(s), Repair and paint (complete)



Shutter / cover F, Missing, Replace



Bumper F, Hole, Replace



Windscreen, Stone chip(s), Windscreen repair



Wing FR, Dent(s), Acceptable



Door FR, Dent(s), Acceptable



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)



Rear light L, Broken, Replace



Bumper R, Broken, Replace



Boot door panel RR, Dent(s), Repair and paint (complete)



Boot door panel RL, Dent(s), Repair and paint (complete)



Jack, Missing, Repair/replace (lump sum)



Spare tyre, Missing, Replace



Spare rim, Missing, Replace



Historique Maintenance

Immatriculation: EG-576-XV Date de 1ère immatriculation: 22/11/2016

Modèle: Volkswagen CADDY MAXI VAN 2.0 TDI MAXI 122 4MOTION VU [4P] bvm 6-122CH-7cv (fourgonnettesimple cabine)

Date	Kilométrage	Fournisseur	Descriptif
29/04/2026	138.829	DEKRA AUTOMOTIVE TRAPPES	CONTROLE TECHNIQUE
30/03/2026	138.063	ETABLISSEMENT LAVILLAUIROY	RESERVOIR ADBLUE RPLT
17/11/2025	129.015	ETABLISSEMENT LAVILLAUIROY	REMPACEMENT PNEUS 4 SAISONS
06/10/2025	128.947	ETABLISSEMENT LAVILLAUIROY	CREMAILLE RE DE DIRECTION RPLT
	0		BOUGIES DE PRECHAUFFAGE RPLT
	0		DIVERS ELEC
22/09/2025	128.326	ETABLISSEMENT LAVILLAUIROY	DIVERS TRANSMISSION
	0		GEOMETRIE CTRL
	0		BIELLETT E DE DIRECTION AVG RPLT
	0		REVISION
16/06/2025	120.000	CONTITRADE FRANCE	GEOMETRIE CTRL
16/06/2025	120.000	CONTITRADE FRANCE	REMPACEMENT PNEUS 4 SAISONS
28/03/2025	115.518	ETABLISSEMENT LAVILLAUIROY	ETRIERS AV RPLT
	0		DISQUES PLAQUETTES AR RPLT
12/02/2025	114.061	CONTITRADE FRANCE	REMPACEMENT PNEUS ETE
12/02/2025	114.061	CONTITRADE FRANCE	GEOMETRIE CTRL
19/08/2024	102.886	ETABLISSEMENT LAVILLAUIROY	REVISION ET CLIM ET AIR
	0		AMORTISSEURS AR RPLT
	0		AMORTISSEURS AV RPLT
	0		DIVERS ELEC
	0		SILENCIEUX RPLT
	0		AMORTISSEURS AV RPLT
07/10/2024	98.093	EUROMASTER FRANCE	REPARATION DE ROUE
30/04/2024	97.706	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
27/02/2024	93.990	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
22/02/2024	93.613	ETABLISSEMENT LAVILLAUIROY	VOLANT MOTEUR RPLT
	0		DIVERS CARROSSERIE
	0		ECLAIRAGE DE PLAQUE RPLT
	0		DISQUES PLAQUETTES AV RPLT
01/08/2023	91.870	ETABLISSEMENT LAVILLAUIROY	DISQUES PLAQUETTES AR RPLT
	0		DISQUES PLAQUETTES AV RPLT
28/12/2022	88.910	ETABLISSEMENT LAVILLAUIROY	ADBLUE

Historique Maintenance

Immatriculation: **EG-576-XV**

Date de 1ère immatriculation: **22/11/2016**

Modèle: **Volkswagen CADDY MAXI VAN 2.0 TDI MAXI 122 4MOTION VU [4P] bvm 6-122CH-7cv
(fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
	0		REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV
09/11/2022	86.595	NORAUTO SAS (PRODUIT SPE)	LAMPE AR RPLT
08/11/2022	86.398	NORAUTO SAS (PRODUIT SPE)	GEOMETRIE CTRL
08/11/2022	86.398	NORAUTO SAS (PRODUIT SPE)	REPLACEMENT PNEUS HIVER
19/04/2022	79.618	ETABLISSEMENT LAVILLAUIROY	DISQUES PLAQUETTES AV RPLT
09/12/2021	74.607	DEKRA AUTOMOTIVE S.A	ANTIPOLLUTION
09/11/2021	73.226	NORAUTO SAS (PRODUIT SPE)	REPLACEMENT PNEUS HIVER
14/10/2021	72.392	ETABLISSEMENT LAVILLAUIROY	DIVERS MOTEUR
	0		KIT DISTRIBUTION RPLT
	0		DIVERS ECHAPPEMENT
26/11/2020	61.554	CONTROLE TECHNIQUE PALOIS	CONTROLE TECHNIQUE
15/03/2021	61.388	ETABLISSEMENT LAVILLAUIROY	DIVERS ELEC
18/11/2020	60.985	ETABLISSEMENT LAVILLAUIROY	PLAQUETTES AR RPLT
26/10/2020	59.780	NORAUTO SAS (PRODUIT SPE)	REPLACEMENT PNEUS ETE
14/09/2020	57.072	ETABLISSEMENT LAVILLAUIROY	ADBLUE
	0		PLAQUETTES AV RPLT
	0		FILTRE A AIR RPLT
	0		FILTRE CLIM RPLT
	0		REVISION
	0		HUILE PONT
07/02/2020	46.367	FRANCE PARE BRISE SAS	PARE BRISE RPLT
14/01/2020	45.838	SCALA TARBES	BOITIER DE PRECHAUFFAGE RPLT
18/11/2019	44.035	NORAUTO SAS (PRODUIT SPE)	REPLACEMENT PNEUS HIVER
16/07/2019	41.332	NORAUTO SAS (PRODUIT SPE)	REPLACEMENT PNEUS ETE
	0		GEOMETRIE CTRL
06/02/2019	34.398	SCALA TARBES	ADBLUE
	0		PLAQUETTES AR RPLT
	0		PLAQUETTES AV RPLT
	0		BATTERIE RPLT
07/11/2018	30.130	SCALA TARBES	BALAIS ESSUIE GLACE AV
	0		REVISION ET CLIM
	0		ADBLUE

Historique Maintenance

Immatriculation: **EG-576-XV**

Date de 1ère immatriculation: **22/11/2016**

Modèle: **Volkswagen CADDY MAXI VAN 2.0 TDI MAXI 122 4MOTION VU [4P] bvm 6-122CH-7cv
(fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
26/09/2018	28.402	NORAUTO SAS (PRODUIT SPE)	REPLACEMENT PNEUS HIVER
24/01/2018	17.689	SCALA TARBES	DISQUES PLAQUETTES AV RPLT
15/11/2017	14.368	EUROMASTER FRANCE	REPLACEMENT PNEUS HIVER
21/09/2017	11.934	SCALA TARBES	PLAQUETTES AR RPLT
	0		ADBLUE
31/07/2017	9.840	FRANCE PARE BRISE SAS	TLG POUBELLE
09/01/2017	713	EUROMASTER FRANCE	REPLACEMENT PNEUS HIVER