



Expertise

Protocol number: 46409357
Order No. / Reference: 26644585
Inspection date: 2 Jul 2026

Manufacturer: Volkswagen

Model: ID.4 GTX 220 KW

VIN: WVGZZZE2ZPE065289



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen ID.4 GTX 220 KW	
Vehicle Identification number	WVGZZZE2ZPE065289
Mileage (Read)	28,091 km
First registration	2 Jun 2023
Number of holders	1
Power / Engine displacement	77 kw /
Fuel type / Cylinder	Electric / 0
Gearbox / Number of gears	Direct drive / 1
Type of drive	All-wheel drive
Type of vehicle	Station wagon
Colour / colour code	Grenadillschwarz Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	343 Tag(e)
Last service on / at	06/2025 at 20,048 km		
Key is / should be	1 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV168184
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	0603 / CLR 00033		
Emission standard	2017/1151;WLTP;reine Elektrofz	fine dust sticker	
Permitted total weight	2,750 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/45 R21 101T	Summer tires (with run-flat tires) on Light alloy	Bridgestone	6mm / 6mm
2)	255/40 R21 102T	Summer tires (with run-flat tires) on Light alloy	Bridgestone	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 105T	Winter tires (with run-flat tires) on Light alloy	Goodyear	7mm / 7mm
2)	255/50 R19 107T	Winter tires (with run-flat tires) on Light alloy	Goodyear	7mm / 7mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 USB-C ports at the front, 2 USB-C charging ports at the rear of the center console (charging power up to 45 W)
- Airbags: Front and rear head airbags, front side airbags, center airbag
- 30-color ambient lighting
- Adaptive Cruise Control (ACC) "stop & go" including speed limiter
- Car2X
- e-Sound (artificially generated engine noise to inform other road users about the approach of the e-vehicle)
- Parking aid (warning signals for obstacles in the front and rear area)
- Driving profile selection
- Windscreen made of laminated safety glass (wirelessly heated and infrared-reflecting, noise-reducing)
- Back window, heater
- Infotainment accessories: Online update capability from ID.Software 2.1
- Air conditioning "Air Care Climatronic" (with active combination filter, stationary air conditioning and 2-zone temperature control)
- Paint finish: Solid color, with differing roof color
- Charging: 11 kW AC charging power (alternating current)
- LED matrix headlights - IQ.LIGHT (With automatic headlight control, bad weather light, welcome function - Dynamic Light Assist for LED matrix headlights)
- Makeup mirrors in the sun visors
- Variable center console (with interchangeable inserts for cup holders and storage compartments)
- Emergency call service (no registration required, service is activated upon delivery)
- Stainless steel pedals in a "Play/Pause" design
- Upholstery: Seat center panels of the front seats and the outer rear seats in "GTX" fabric
- Radio accessories: 6 + 1 speakers
- Rain sensor
- LED taillights: 3D LED taillights with dynamic turn signals
- Front windshield washer nozzles automatically heated
- Electromechanical power steering (speed-dependent control)
- Seats: Armrest for front seats
- Seats: Rear seat backrest asymmetrically split and foldable, with pass-through and center armrest (with 2 cup holders)
- Voice control
- Bumpers in a sporty design
- Engine underguard
- Ambient lighting with logo projection
- Traffic sign recognition
- Central locking including remote control
- Turning brake function and evasive steering support
- Airbag for driver and front passenger, with front passenger airbag deactivation
- Permanent 4MOTION all-wheel drive
- App-Connect Wireless for Apple CarPlay and Android Auto
- Electrically adjustable, folding and heated exterior mirrors
- third brake light
- black roof rails
- Black surround for the infotainment display and central controls
- ESP Electronic Stability Program (incl. ABS Anti-lock Braking System)
- Dynamic high beam control "Dynamic Light Assist" for LED matrix headlights
- Transmission: 1-speed automatic
- rear window wiper
- Interior mirror automatically dimming
- ISOFIX mounting points for child seats (mounting points for child seats on the outer rear seats and on the front passenger seat, i-Size compatible)
- Front and rear headrests (5)
- Mode 3 Type 2 charging cable, 16 A
- Charging: Maximum DC charging power depends on the traction battery.
- The strip between the headlights is illuminated.
- Steering wheel: Multifunction leather steering wheel, heated, with touch controls
- Fatigue detection
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Package: Infotainment package (Navigation system "Discover Pro" - Telephone interface "Comfort" with inductive charging function)
- Radio "Ready 2 Discover"
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring system
- Windows: Rear side windows and rear window tinted
- Keyless Start system (without safe locking)
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner (3 three-point automatic seat belts at the rear - warning tone and light for unfastened seat belts at the front and rear)
- Seats: Heated front seats
- Seats: Front seats with height adjustment
- Lane keeping assistant "Lane Assist"
- "Comfort" telephone interface with inductive charging function
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer



Extra equipment

- Foldable towbar (electric release)
- Package: Design Package "Plus" (3D LED taillights with dynamic turn signals - Dynamic Light Assist for LED matrix headlights - IQ.LIGHT - LED matrix headlights with automatic headlight control, bad weather lights, welcome function - Illuminated strip between the headlights - Panoramic roof - Laminated safety glass for front side windows; tinted rear window and rear side windows)
- Package: Comfort Package "Plus" incl. telematics box (2 USB-C ports front, 2 USB-C charging sockets rear center console - Windscreen in laminated safety glass, wirelessly heated and infrared-reflecting, noise-insulating - Luggage net - Luggage compartment floor - Climatronic with active combination filter and 3-zone temperature control - Variable center console - Multifunction leather steering wheel, heated, with touch controls - Cargo net partition - Without headlight washers with washer fluid level indicator - Rain sensor - Automatically heated windscreen washer nozzles - Heated front seats - Telematics box)
- Package: Assistance Package (GTX) (Anti-theft alarm system with interior monitoring, backup horn and tow-away protection - Illuminated strip between the headlights and door handle recesses - "Park Assist Plus" parking assistant including parking aid - Proactive occupant protection system in conjunction with "Front Assist" - "Rear View" reversing camera - "Keyless Access" keyless locking and starting system with safe locking)
- Package: Sport package "Plus" (Adaptive chassis control DCC incl. driving profile selection - progressive steering)
- Wheels: Alloy wheels (4) "Narvik" 8.5 J x 21 front, 9 J x 21 rear, in black / diamond-turned (wheels in black, diamond-turned surface - Airstop tires 235/45 R 21 front, Airstop tires 255/40 R 21 rear - wheel locks with enhanced theft protection)
- Textile floor mats front and rear
- Heat pump for range optimization

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance (1. Wartung um 8 Tage überschritten)
2	Boot lid / rear door	Boot lid - Glued / labelled - De-glue / neutralise
3	Sill - left side	Sill - Scratch(es) - Smart repair
4	Side panel - rear left side	Sill - Scratch(es) - Smart repair
5	Boot lid / rear door	Boot lid - Scratch(es) - Smart repair
6	Rear bumper	Bumper - rear right side - Scratch(es) - Smart repair
7	Rear bumper	Bumper - rear left side - Scratch(es) - Smart repair
8	Trim / covers	Boot lid - interior trim - Scratch(es) - Replace
9	Rear bumper	Rear bumper - Scratch(es) - Loss in value
10	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Loss in value
11	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
12	Roof	Roof - Scratch(es) - Loss in value
13	Wheel / tyres	Tyre - rear right side - Broken / torn - Replace
14	Roof	Sun roof / glass - Scratch(es) - Replace



Wear and tear

No.	Component group	Description
1	Instrument panel	Centre console - front - Scratch(es) - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - charging cable (Mode3 Typ2)

Equipment - Vehicle key

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres




Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Damage 2: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise




Damage 2: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise




Damage 3: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 3: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 4: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 4: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 5: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair




Damage 5: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair




Damage 6: Rear bumper: Bumper - rear right side - Scratch(es) - Smart repair



Damage 6: Rear bumper: Bumper - rear right side - Scratch(es) - Smart repair



Damage 7: Rear bumper: Bumper - rear left side - Scratch(es) - Smart repair




Damage 7: Rear bumper: Bumper - rear left side - Scratch(es) - Smart repair



Damage 8: Trim / covers: Boot lid - interior trim - Scratch(es) - Replace



Damage 8: Trim / covers: Boot lid - interior trim - Scratch(es) - Replace



Damage 9: Rear bumper: Rear bumper - Scratch(es) - Loss in value



Damage 9: Rear bumper: Rear bumper - Scratch(es) - Loss in value



Damage 10: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 10: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 10: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value




Damage 11: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 11: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 12: Roof: Roof - Scratch(es) - Loss in value



Damage 12: Roof: Roof - Scratch(es) - Loss in value



Damage 13: Wheel / tyres: Tyre - rear right side - Broken / torn - Replace



Damage 13: Wheel / tyres: Tyre - rear right side - Broken / torn - Replace



Damage 14: Roof: Sun roof / glass - Scratch(es) - Replace



Damage 14: Roof: Sun roof / glass - Scratch(es) - Replace



Damage 14: Roof: Sun roof / glass - Scratch(es) - Replace



Damage 14: Roof: Sun roof / glass - Scratch(es) - Replace



Damage 14: Roof: Sun roof / glass - Scratch(es) - Replace



Damage 14: Roof: Sun roof / glass - Scratch(es) - Replace