

INSPECTION REPORT


End of contract

GENERAL INFO

File	315375
License plate	2CED536
Vehicle identification number	WBA11AM0207L31460
Dossier	2022 013 027
Make	BMW 216d Gr.C.85kW Aut.
Mileage	58425
First registration	21/06/2022
client availability date	29/06/2026
inspectionDate	06/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
196	Door Rear Right // Polish	Y
216	Door Front Right // Polish	Y
12	Bumper Front // Smart Repair Large	Y
18	Bumper Front / Spoiler / Replace	Y
61	Wing Front Left // Smart Repair Medium	Y
80	Door Front Left // Smart Repair Small	Y
131	Bumper Rear // Smart Repair Medium	Y
181	Wing Rear Right // Smart Repair Medium	N

Damage Pictures



Wing Rear Right // Smart Repair Medium-scratch + dent



Wing Front Left // Smart Repair Medium-scratch + dent



Bumper Front // Smart Repair Large-scratch



Bumper Front / Spoiler / Replace-scratch




Door Front Left // Smart Repair Small-scratch



Bumper Rear // Smart Repair Medium-scratch



Door Rear Right // Polish-scratch





Door Front Right // Polish-scratch