MACADAM







Seat Leon (UKL): 2BDR783

Vinnumber:	**VSSZZZKLZNR020525**	Versionname:	**Leon ST Xcellence 1.4 E-Hybrid 204pk/cv 5p DSG6**
First Registrationdate:	**14/10/2021**	Fiscalpower:	
Expertise Mileage:	**124460**	Power Kw:	**110**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Plug-in Hybrid Petrol**		
Maintenance	**OK**		
Maintenance	**plus 7600**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/45/17/91 V**			
	Fr.L.	**Continental: 3 mm**	Fr.R.	**Continental: 3 mm**
	Re.L.	**Continental: 3 mm**	Re.R.	**Continental: 3 mm**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**3.0**
Tyre profile depth RL	**3.0**
Tyre profile depth RR	**3.0**
Tyre size FL	**225/45 R 17 91 V**
Tyre size FR	**225/45 R 17 91 V**
Tyre size RL	**225/45 R 17 94 V**
Tyre size RR	**225/45 R 17 94 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Number of charging cables (normal)	**2**
Number of charging cables (rapid charge)	**1**

Seat cover RL, Stain, Cleaning




Seat cover RR, Stain, Cleaning




Bumper F, Scratch(es), Spot repair





Bonnet, Scratch(es), Acceptable




Alloy rim FL, Scratch(es), Repair and paint (complete)




Wing RL, Dent(s) and scratch(es), Acceptable






Tailgate / Boot, Dent(s), Acceptable




Bumper R, Scratch(es), Acceptable




Wing RR, Dent(s) and scratch(es), Acceptable






Outer door handle FR, Scratch(es), Acceptable




Alloy rim FR, Scratch(es), Acceptable




Onderhoudshistorie van: VSSZZZKLZNR020525

ALPHABET

Kenteken	2BDR783
Merk Model	Seat Leon ST Xcellence 1.4 E-Hybrid 204pk/cv 5p DSG6
Brandstofsoort	Benzine
Datum deel1	10/14/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
8/19/26	121,993	diagnose	Uitvoeren
8/19/26	121,993	foutencodes uitlezen	Uitvoeren
8/19/26	121,993	inlaat luchtkoeling	Vervangen
8/19/26	121,993	klein materiaal	
7/10/26	116,996	0139-Aanvulling op onderhoudsbeurt	Uitvoeren
7/10/26	116,996	bougie	Vervangen
7/10/26	116,996	klein materiaal	
7/10/26	116,996	luchtfilter	Vervangen
7/10/26	116,996	luchtfilter interieur	Vervangen
7/10/26	116,996	remvloeistof	Vervangen
7/10/26	116,996	ruitenwisserrubber vooraan	Vervangen
7/10/26	116,996	Tussentijdse onderhoudsbeurt (variabel	Uitvoeren
7/10/26	116,996	versnellingsbakolie	Vervangen
11/7/25	101,151	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
11/7/25	101,151	ruitenwisserrubber achter	Vervangen
5/29/24	62,106	bougie	Vervangen
5/29/24	62,106	Inspectie met olieververvanging (vast in	Uitvoeren
5/29/24	62,106	luchtfilter interieur	Vervangen
5/29/24	62,106	versnellingsbakolie	Vervangen
3/14/23	30,785	Inspectie met olieververvanging (vast in	Uitvoeren