ARVAL
BNP PARIBAS GROUP

2DEA613

INSPECTION REPORT

End Of Contract


GENERAL INFO

File	293828
License plate	2DEA613
Vehicle identification number	WBY61EF0305W46517
Dossier	2022264040
Make	BMW iX1 xDrive30
Mileage	47694
First registration	17/02/2023
client availability date	09/09/2025
inspectionDate	16/09/2025










CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	




B
2 DEA 613

DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
101	Door Rear Left // Smart Repair Medium	N
136	Bumper Rear // Polish	Y
191	Door Rear Right // Smart Repair Medium	N
216	Door Front Right // Polish	Y
222	Side View Mirror Right // Painting	N
237	Wing Front right / Trim / Replace	N
271	Bumper Front / Trim Left / Replace	N
272	Bumper Front / Trim Right / Replace	N
311	Wheel Alloy Front Left // Repair	N
318	Flat Tyre Kit // Replace	Y
321	Wheel Alloy Rear Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
538	Trunk Compartment / Boot Cover / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures




Bumper Front / Trim Right / Replace-scratch




Bumper Front / Trim Left / Replace-scratch






Bumper Front // Polish-scratch






Wheel Alloy Front Right // Repair-scratch

Side View Mirror Right // Painting-scratch


Door Front Right // Polish-scratch





Bumper Rear // Polish-scratch






Wheel Alloy Rear Left // Repair-scratch






Wheel Alloy Front Left // Repair-scratch


Door Rear Left // Smart Repair Medium-scratch + dent


Door Rear Right // Smart Repair Medium-scratch + dent




Trunk Compartment / Boot Cover / Replace-missing



Flat Tyre Kit // Replace-missing



Interior Cleaning // Small-stain





Wing Front right / Trim / Replace-bad position